

Heavy Truck Inspection Form

Inventory ID:

Asset Number: 2330

Fair Market Value:

Short Description:

Year 2012

Manufacturer Crane Carrier

Model _____

VIN: 1LYCAK486CT050392

Title: ☐ Clean Title ☐ Salvage Title ☐ No Title ☐ Court Documents Only
☐ SF97 Form ☐ Other

Odometer: 76907 ☒ Miles ☐ Kilometers ☐ Hours Odometer Accurate? ☒ Yes ☐ No ☐ Unknown

Long Description: Primary Use for Vehicle: Recycle Collection GVW: 41020

This Vehicle: ☐ Starts ☒ Starts with a Boost & ☐ Is Operable ☐ Is Not Operable ☐ For Parts Only

Date Removed From Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection

Engine Manufacture: Cummins Engine: 8.3 L, V ☐ Gas ☒ Diesel

This vehicle was maintained every 5,000 ☐ Days ☐ Hours ☒ Miles # of Axles 2

Engine Condition: ☒ Is operable ☐ Needs repair ☐ Is in Unknown Condition Jake Brake: ☐ Yes ☒ No

Engine Repairs needed: None when removed from service

Transmission Manufacture: Allison ☒ Automatic ☐ Manual _____ Speed

Transmission Condition is: ☒ Operable ☐ Needs Repair ☐ Unknown Rebuilt Date: _____)

Transmission Repairs Needed: None when removed from service

Exterior: Color White Windows: ☒ No Cracked Glass ☐ Cracked _____

Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: ☐ Low _____ ☐ Flat _____

Damage to: _____

Additional Damage to: _____

Decals: ☐ None ☐ Have been sprayed ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions

Capacity: _____ Loader: ☐ Front ☐ Side Electronic Tarp: ☐ Yes ☒ No Condition: _____

Interior: Color Dark Gray ☒ Cloth ☐ Vinyl ☐ Leather

Damage to Seats: Driver & Passenger seat bottoms are torn

Damage to Dash/Floor: NO

Radio: Brand Unknown ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

☐ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors

Airbags: ☐ Driver's Side ☐ Dual

☒ AC ☐ No AC AC Condition: ☒ Cold ☐ Unknown Power: ☐ Windows ☐ Doorlocks ☒ Steering ☐ Seats

Additional Equipment: Manufacturer: G-S Products Model: G55035D

Serial # G55035315E12 Description: Recycle Body

Equipment Condition: ☒ Is operable ☐ Needs repair ☐ Is in Unknown Condition

Other Equipment: _____

Location of Asset: _____