

Bus Inspection Form

Inventory ID	Asset Number	Fair Market Value:
Short Description: Year <u>2008</u> Make <u>Thomas/Freightliner</u> Model <u>C</u>		
VIN: <u>4UZABRDC58CZ11292</u> Title: <input checked="" type="checkbox"/> Clean Title <input type="checkbox"/> Salvage Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> No Title <input type="checkbox"/> Other		
Mileage/Odometer: <u>106,560</u> <input checked="" type="checkbox"/> Mi <input type="checkbox"/> Km <input type="checkbox"/> Hrs Odometer Accurate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown		
Long Description:		
Primary use for Bus: <u>Rural Route</u> # of Passengers: _____		
This vehicle: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost and <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only		
Engine Manufacture: <u>CAT</u> Engine Type: <u>C7210</u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine		
This Vehicle was maintained every <u>unknown</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input type="checkbox"/> Miles		
Engine Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition		
Repairs needed: <u>driver side coolant leak; needs batteries; brake issues; needs tires</u>		
Date Removed From Service: <u>8/22</u> Maintenance Records: <input checked="" type="checkbox"/> Available <input type="checkbox"/> Not Available		
Transmission Manufacture: <u>Allison</u> <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual <u>Speed</u>		
Transmission Condition is: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Unknown Rebuilt (Date: _____)		
Repairs Needed: <u>none known</u>		
Date Removed From Service: <u>8/22</u> Maintenance Records: <input checked="" type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection		
Exterior Description:		
Color: <u>Yellow/black</u> Windows: <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked _____		
Minor: <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: Low <input checked="" type="checkbox"/> Flat _____		
Damage to: <u>needs tires</u>		
Additional Damage to: _____		
Decals: <input type="checkbox"/> None <input type="checkbox"/> Have been Sprayed Over <input checked="" type="checkbox"/> Have been removed & <input type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions		
Other Exterior Information: _____		
Interior Description:		
Color <u>gray & blue</u> <input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Cloth <input type="checkbox"/> Leather		
Damage to Seats: <u>some damage; normal wear</u>		
Damage to Dash/Floor: <u>floor issues; dash good; 2 speaker covers off</u>		
Radio: Brand <u>Panasonic</u> <input type="checkbox"/> AM <input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input checked="" type="checkbox"/> AM/FM CD		
Air Conditioning: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No AC Operating Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown		
Other Interior Information/Options: _____		
Other Equipment: Description _____		
Manufacturer _____ Model _____ Serial # _____		
Location of Asset: <u>Douglass KS</u>		