

# GovDeals Heavy Equipment Inspection Form

|  |                                  |                       |
|--|----------------------------------|-----------------------|
| Inventory ID: <u>DOZER03</u>   | Asset Number: <u>DOZER03</u>     | Fair Market Value:    |
| Short Description:   |                                  |                       |
| Year: <u>2015</u>  | Manufacturer: <u>Caterpillar</u> | Model: <u>D4K2LGP</u> |
| Long Description: Equipment Serial # <u>OKRR00610</u>  |                                  |                       |
| This Equipment: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Is Operable <input type="checkbox"/> Is not operable <input type="checkbox"/> For Parts Only                      |                                  |                       |
| Engine: <u>C44 ACERT</u> Gas <input checked="" type="checkbox"/> Diesel engine Engine: <u>8</u> Hours <u>10469</u> Miles <u>        </u>   |                                  |                       |
| This vehicle was maintained every <u>500</u> Hours   |                                  |                       |
| Engine Manufacture: <u>CAT</u> Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition  |                                  |                       |
| Engine Repairs needed: <u>        </u>   |                                  |                       |
| Transmission: <input type="checkbox"/> Automatic <input type="checkbox"/> Manual <u>        </u> Speed Transmission: <input type="checkbox"/> Hours <u>        </u> Miles <u>        </u>  |                                  |                       |
| Transmission Manufacture: <u>        </u> Condition: <input type="checkbox"/> Is Operable <input checked="" type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown   |                                  |                       |
| Transmission Repairs Needed: <u>Will not move Charge Pump failed</u>   |                                  |                       |
| Drivetrain: <input type="checkbox"/> 2WD <input type="checkbox"/> 4WD <input type="checkbox"/> AWD Condition: <u>        </u>  |                                  |                       |
| Date Removed From Service: <u>1/20/25</u> Maintenance Records: <input checked="" type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection   |                                  |                       |
| Exterior: Color <u>Yellow</u> Windows: <input type="checkbox"/> No cracked glass <input type="checkbox"/> Cracked <u>        </u>  |                                  |                       |
| Minor <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low <input type="checkbox"/> Flat <u>        </u>                              |                                  |                       |
| Damage to: <u>        </u>   |                                  |                       |
| Additional Damage to: <u>        </u>  |                                  |                       |
| # Of Wheels <u>        </u> # Of Axles <u>        </u> # Of Tracks <u>        </u>   |                                  |                       |
| Dimensions: <u>        </u>  |                                  |                       |
| Decals: <input type="checkbox"/> None <input type="checkbox"/> Have been sprayed <input type="checkbox"/> Have been removed <input type="checkbox"/> Impressions remain <input type="checkbox"/> No impressions                                      |                                  |                       |
| Interior: Color <u>        </u> <input type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather   |                                  |                       |
| Damage to Seats: <u>        </u>   |                                  |                       |
| Damage to Dash/ Floor: <u>        </u>   |                                  |                       |
| Radio: Brand <u>        </u> <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD  |                                  |                       |
| <input type="checkbox"/> Cruise Control Power: <input type="checkbox"/> Steering <input type="checkbox"/> Seats <input type="checkbox"/> AC <input type="checkbox"/> No AC Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown |                                  |                       |
| Additional Equipment: Manufacturer <u>        </u> Model <u>        </u>   |                                  |                       |
| Serial # <u>        </u> Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition  |                                  |                       |
| Description: <u>        </u>   |                                  |                       |
| Location of Asset: <u>        </u>   |                                  |                       |
| For more information contact: <u>        </u>  |                                  |                       |