



Vehicle Information

Fleet #: 69
Fleet Name: Wastewater - 1 Ton Dump Truck
Mileage: 60888.0
Hours: 5018.0
Original Purchase Date: 01/01/2008
Original Purchase Price: 22,275.00
Year: 2008
Make: FORD
Model: F-350 4WD
VIN #: 1EDWF37Y48EE57278
Department: Wastewater
Classification: Dump Truck
Status: Active
Fuel Level:
Plate Number: M174130

Vehicle Replacement Rating

Age	Activity	Usage	Cost	Condition	Overall
17.0	2.0	22.8	0.80000001	5.0	41.5

Scheduled Maintenance

Maintenance Type	Mileage Interval	Hours Interval	Day Interval	Next Mileage	Next Hours	Next Date
Scheduled Maintenance	0	0	365	0	0	07/23/2026

Maintenance Work Order History

WO #	Request Date	Maintenance Type	Description	Mileage	Hours	Completed Date	Total Cost
2086	06/25/2025	Scheduled Maintenance	Checked over. Did not service. truck is in bad shape. Recommended to get rid of.	60888.0	5018.0	07/23/2025	.00
1751	06/14/2024	Scheduled Maintenance	Change oil and filter. Check fluids. Check tire psi. replace fuel filter.	60270.0	5018.0	06/19/2024	30.52
1451	05/24/2023	Repair to Start	Remove and replace starter at sewer plant.	59713.0	0.0	05/24/2023	199.96
1324	10/20/2022	Battery Replacement	Replace battery	59160.0	0.0	10/20/2022	131.55
873	03/17/2021	Transmission Problem	Repalce transmission cooler lines from trans to trans cooler. PM service and check tire pressures. check fluids.	57852.0	0.0	03/17/2021	146.38
707	07/28/2020	Steering Repair	Truck was towed in. Replace left outer tie rod end and take to Raisor Motor Co. for front end alignment.	57217.0	0.0	07/21/2020	186.57
608	03/06/2020	Repair to Start	Replace Battery and clean battery cables. Remove old door decals and numbers and install new decals and numbers.	56718.0	0.0	03/06/2020	120.27
592	02/21/2020	State Lane Inspection	Inspection completed by Cady Oil Company. Emergency Brake failed inspection.	56481.0	0.0	02/20/2020	.00

587	02/20/2020	Brake Repair	Adjust rear parking brake shoes. Replace hood release cable assembly.	56742.0	0.0	04/09/2020	.00
575	02/06/2020	Repair Snowplow	Clean both connectors for the plow hook ups. Zip tie both connector harnesses together so the power and ground cable does not sag.	56481.0	0.0	02/06/2020	.00
550	01/17/2020	Tire Change	Run to East Peoria tire to get tires. Mount 4 tires.	56085.0	0.0	01/17/2020	536.72
502	11/20/2019	Scheduled Maintenance	Serviced,checked and added fluids,greased chassis,changed air and fuel filters. Rotated front tires to rear, cleaned rims and inspected brakes.	55501.0	0.0	11/20/2019	49.10
337	07/09/2019	Electrical Problem	Replace left front turn signal bulb.	54440.0	0.0	07/09/2019	.00
232	03/25/2019	Tire Repair	Found a screw in right rear tire. Pulled screw out and plug the tire.	53636.0	0.0	03/25/2019	.00
174	02/08/2019	Front End Repair	Replaced ring gear,pinion and pinion bearings. Replaced carrier assembly and carrier bearings. Replaced crush sleeve and pinion seal. Replaced outer hub seals, Brake rotors, pads and brake calipers. Replaced front u-joint on front driveshaft. Replaced pass side upper and lower ball joints.Replaced right outer tie rod end. Take to Raisor Motor Co. to have front end aligned.	52740.0	0.0	02/07/2019	1838.32

Assigned Parts

Part	Part #	Category	Vendor	Description
Air Filter	29883	General	Napa	
Alignment		6- Wastewater	Raisor Motor Co.	
Battery	MTP-65HD	General	Interstate Batteries	
Bolts	F81Z-4N272-AA	General	Mike Murphy Ford	
Brake Caliper	SE5548A	General	Napa	
Brake Caliper	SE5547A	General	Napa	
Brake Pads	FT-7974-A	General	Napa	
Brake rotor	48880339	General	Napa	
Differential Carrier assembly	5C3Z-4026-B	General	Mike Murphy Ford	
Dust seal- Axle	AC3Z-1S175-A	General	Mike Murphy Ford	
Engine oil	5W 20	General	Lozier Oil	
Engine oil	5w-20	General	Lozier Oil	
Front end alignment		General	Raisor Motor Co.	
Fuel filter	23243	General	Napa	
Hub Seal	5C3Z-3254-B	General	Mike Murphy Ford	
Left outer tie rod end.	169-5599	General	Napa	
Lower Ball Joint	260-1395	General	Napa	
Mercon SP	XT-6-QSP	General	Mike Murphy Ford	Trans fluid
Oil filter	1372	General	Napa	
Oil filter	1372	General	Napa	
Right Outer Tie Rod End	269-5600	General	Napa	
Ring Gear and Pinion set	DC3Z-3222-B	General	Mike Murphy Ford	
Starter	4N9292	6- Wastewater	Napa	
Tires	LT245/75 R17	General	East Peoria tire	
Trans cooler lines	7C3Z-7R081-D	General	Mike Murphy Ford	
Trans cooler lines	8C3Z-7R081-B	General	Mike Murphy Ford	
Universal Joint	5C3Z-4635-AA	General	Mike Murphy Ford	
Upper Ball Joint	260-1248	General	Napa	