

Heavy Truck Inspection Form

Inventory ID: 118	Asset Number:	Fair Market Value: \$5,000
--------------------------	----------------------	-----------------------------------

Short Description:
 Year 2013 Manufacturer INTERNATIONAL Model 7400 WORKSTAR

VIN: 1HTWDAAR2DH477153 Title: ☒ Clean Title ☐ Salvage Title ☐ No Title ☐ Court Documents Only
☐ SF97 Form ☐ Other

Odometer: 76293 ☒ Miles ☐ Kilometers ☐ Hours **Odometer Accurate?** ☒ Yes ☐ No ☐ Unknown

Long Description: Primary Use for Vehicle: HAUL STONE, DIRT & PLOW SNOW GVW: _____

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only

Date Removed From Service: 4/21/2025 Maintenance Records: ☒ Available ☐ Not Available For Inspection

Engine Manufacture: INTERNATIONAL MAXFORCE **Engine:** 6 L, V ☐ Gas ☒ Diesel

This vehicle was maintained every 5000 ☐ Days ☐ Hours ☒ Miles # of Axles 2

Engine Condition: ☒ Is operable ☐ Needs repair ☐ Is in Unknown Condition Jake Brake: ☐ Yes ☒ No

Engine Repairs needed: _____

Transmission Manufacture: EATON FULLER ☐ Automatic ☒ Manual 8 Speed

Transmission Condition is: ☒ Operable ☐ Needs Repair ☐ Unknown Rebuilt Date: _____)

Transmission Repairs Needed: _____

Exterior: Color RED **Windows:** ☒ No Cracked Glass ☐ Cracked _____

Minor: ☒ Dents ☒ Scratches ☒ Dings **Tire Condition:** ☒ Low ☐ Flat _____

Damage to: FRONT TIRES 5/32 & REAR TIRES 9/32

Additional Damage to: _____

Decals: ☒ None ☐ Have been sprayed ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions

Capacity: _____ Loader: ☐ Front ☐ Side Electronic Tarp: ☐ Yes ☐ No Condition: _____

Interior: Color GREY ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: NO

Damage to Dash/Floor: NO

Radio: Brand PANASONIC ☐ AM ☐ AM/FM ☒ AM/FM Cassette ☐ AM/FM CD

☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors **Airbags:** ☐ Driver's Side ☐ Dual

☒ AC ☐ No AC AC Condition: ☒ Cold ☐ Unknown **Power:** ☐ Windows ☐ Doorlocks ☒ Steering ☐ Seats

Additional Equipment: Manufacturer: HENDERSON Model: 10X30XUBXMKE

Serial # MKE 2641 Description: SWING GATE DUMP BED

Equipment Condition: ☐ Is operable ☐ Needs repair ☐ Is in Unknown Condition

Other Equipment: _____

Location of Asset: Monroe County Highway Dept. 5900 W. Foster Curry Dr. Bloomington, IN 47403