

Bus Inspection Form

Inventory ID	Asset Number 16	Fair Market Value:
Short Description:		
Year 1993	Make International	Model 3800
VIN: 1HVBPEP8PH496527		
Title: ☐ Clean Title ☐ Salvage Title ☐ Court Documents Only ☐ SF97 Form ☐ No Title ☐ Other		
Mileage/Odometer: 35404 ☒ Mi ☐ Km ☐ Hrs Odometer Accurate? ☐ Yes ☒ No ☐ Unknown		
Long Description:		
Primary use for Bus: Sub and Shuttle # of Passengers: 71		
This vehicle: ☒ Starts ☐ Starts with a Boost and ☒ Runs ☐ Does Not Run ☐ For Parts Only		
Engine Manufacture: International DT360 Engine Type: L, V ☐ Gas ☒ Diesel Engine		
This Vehicle was maintained every 10,000 ☐ Days ☐ Hours ☒ Miles		
Engine Condition: ☒ Runs ☐ Needs repair ☐ Is in Unknown Condition		
Repairs needed: _____		
Date Removed From Service: June 2025 Maintenance Records: ☐ Available ☐ Not Available		
Transmission Manufacture: Allison ☒ Automatic ☐ Manual Speed		
Transmission Condition is: ☒ Operable ☐ Needs Repair ☐ Unknown Rebuilt (Date: _____)		
Repairs Needed: _____		
Date Removed From Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection		
Exterior Description:		
Color: _____ Windows: ☐ No Cracked Glass ☐ Cracked		
Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: Low _____ Flat _____		
Damage to: _____		
Additional Damage to: _____		
Decals: ☐ None ☐ Have been Sprayed Over ☐ Have been removed & ☐ Impressions Remain ☐ No Impressions		
Other Exterior Information: _____		
Interior Description:		
Color Brown ☒ Vinyl ☐ Cloth ☐ Leather		
Damage to Seats: _____		
Damage to Dash/Floor: _____		
Radio: Brand _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD		
Air Conditioning: ☐ Yes ☐ No AC Operating Condition: ☐ Cold ☐ Unknown		
Other Interior Information/Options: _____		
Other Equipment: Description _____		
Manufacturer _____ Model _____ Serial # _____		
Location of Asset: _____		