

9

Inventory ID

Asset Number

Fair Market Value:

Short Description:

Year 1998

Make International

Model 3800

VIN: 1HVBBABP1WH570810

Title: ☐ Clean Title ☐ Salvage Title ☐ Court Documents Only
☐ SF97 Form ☐ No Title ☐ Other

Mileage/Odometer: 172667

☒ Mi ☐ Km ☐ Hrs Odometer Accurate? ☒ Yes ☐ No ☐ Unknown

Long Description:

Primary use for Bus, Sub and Shuttle

of Passengers: 71

This vehicle: ☒ Starts ☐ Starts with a Boost and ☒ Runs ☐ Does Not Run ☐ For Parts Only

Engine Manufacture: International T444E

Engine Type: L, V ☐ Gas ☒ Diesel Engine

This Vehicle was maintained every 10,000 ☐ Days ☐ Hours ☒ Miles

Engine Condition: ☒ Runs ☐ Needs repair ☐ Is in Unknown Condition

Repairs needed:

Date Removed From Service: June 2025

Maintenance Records: ☐ Available ☐ Not Available

Transmission Manufacture: Allison

☒ Automatic ☐ Manual Speed

Transmission Condition is: ☒ Operable ☐ Needs Repair ☐ Unknown Rebuilt (Date: _____)

Repairs Needed:

Date Removed From Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection

Exterior Description:

Color: _____ **Windows:** ☐ No Cracked Glass ☐ Cracked _____

Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: Low Flat

Damage to: _____

Additional Damage to: _____

Decals: ☐ None ☐ Have been Sprayed Over ☐ Have been removed & ☐ Impressions Remain ☐ No Impressions

Other Exterior Information:

Interior Description:

Color Brown ☒ Vinyl ☐ Cloth ☐ Leather

Damage to Seats:

Damage to Dash/Floor:

Radio: Brand ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

Air Conditioning: ☐ Yes ☐ No AC Operating Condition: ☐ Cold ☐ Unknown

Other Interior Information/Options:

Other Equipment: Description

Manufacturer	Model	Serial #
--------------	-------	----------

Location of Asset: _____