

Vehicle Inspection Form

Inventory ID: 707	Asset Number: 47429	Fair Market Value:
Short Description: Year <u>2006</u> Make <u>Ford</u> Model <u>Explorer</u>		
VIN: <u>1FMEU62E96UA05409</u> Title: <input checked="" type="checkbox"/> Clean Title <input type="checkbox"/> Salvage Title <input type="checkbox"/> No Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> Other		
Odometer: <u>92,488</u> <input checked="" type="checkbox"/> Miles <input type="checkbox"/> Kilometers <input type="checkbox"/> Hours Odometer Accurate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown		
Long Description: This Vehicle: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Runs/Drivable <input checked="" type="checkbox"/> Engine Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only Engine- Type: <u>4.0</u> L, V <u>6</u> <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine <input type="checkbox"/> Propane/Natural Gas <input type="checkbox"/> Gas/Electric Hybrid Engine Condition: <input checked="" type="checkbox"/> Runs <input checked="" type="checkbox"/> Needs repair <input type="checkbox"/> is in unknown condition Repairs needed: <u>Unknown</u> This vehicle was maintained every <u>5,000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles/Kilometers Date Removed from Service: <u>2023</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual <u> </u> Speed Condition: <input checked="" type="checkbox"/> Operable <input checked="" type="checkbox"/> Needs repair <input type="checkbox"/> Is Unknown Condition Repairs Needed: <u>Unknown</u> Drivetrain: <input checked="" type="checkbox"/> 2 Wheel Drive <input type="checkbox"/> 4 Wheel Drive Condition: <u>Unknown</u> <hr/> Exterior: Color: <u>Black/White</u> Windows: <input type="checkbox"/> No Cracked Glass <input checked="" type="checkbox"/> Cracked <u>Minor Knicks</u> Minor: <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <u>Okay</u> Tread: <u> </u> #Flat <u> </u> Hubcaps # <u> </u> Major Damage to: <u> </u> Additional Damage: <u> </u> Decals: <input type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed or <input type="checkbox"/> Have been Removed & <input checked="" type="checkbox"/> Impressions Remain <input type="checkbox"/> No impressions Emergency equip: <input checked="" type="checkbox"/> None <input type="checkbox"/> Has been removed & <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes <hr/> Interior: Color <u>Grey</u> <input checked="" type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: <u>Minor Stains</u> Damage to Dash/Floor: <u>Minor Stains / Scratches</u> Radio: <input checked="" type="checkbox"/> Stock or <input type="checkbox"/> Brand & Model: <u> </u> <input type="checkbox"/> AM <input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD AC Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown <input type="checkbox"/> No AC Air Bags: <input type="checkbox"/> Driver's Side <input checked="" type="checkbox"/> Dual <input checked="" type="checkbox"/> Cruise Control <input checked="" type="checkbox"/> Tilt Steering <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Control Power: <input checked="" type="checkbox"/> Steering <input checked="" type="checkbox"/> Windows <input checked="" type="checkbox"/> Door Locks <input type="checkbox"/> Seats		
Additional Equipment: <u>N/A</u> Manufacturer <u> </u> Model <u> </u> Serial # <u> </u> <input type="checkbox"/> Tool Box <input type="checkbox"/> Light Bar <input type="checkbox"/> Ladder Rack <input type="checkbox"/> Utility Body: Brand <u> </u> <input type="checkbox"/> Hitch: Type <u> </u>		
Location of Asset: <u>1002 Dupont Ave, Pascagoula, MS</u>		