

Heavy Equipment Inspection Form

Inventory ID:	Asset Number	Fair Market Value:
Short Description:		
Year <u>1996</u>	Manufacturer <u>Case</u>	Model <u>Case 680K</u>
Long Description: Equipment Serial # <u>N/A</u> [Required for all Marketing]		
This Equipment: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Is Operable <input type="checkbox"/> Is not operable <input type="checkbox"/> For Parts Only		
Engine: <u>L, V</u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel engine Engine: <input type="checkbox"/> Hours <u>964</u> <input type="checkbox"/> Miles _____		
This vehicle was maintained every _____ <input type="checkbox"/> Hours		
Engine Manufacture: <u>Case</u> Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/> Is in Unknown Condition		
Engine Repairs needed: _____		
Transmission: <input type="checkbox"/> Automatic <input checked="" type="checkbox"/> Manual _____ Speed Transmission: <input type="checkbox"/> Hours _____ <input type="checkbox"/> Miles _____		
Transmission Manufacture: _____ Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs Repair <input checked="" type="checkbox"/> Is Unknown		
Transmission Repairs Needed: _____		
Drivetrain: <input checked="" type="checkbox"/> 2WD <input type="checkbox"/> 4WD <input type="checkbox"/> AWD Condition: _____		
Date Removed From Service: _____ Maintenance Records: <input type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection		
Exterior: Color <u>Yellow</u> Windows: <input type="checkbox"/> No cracked glass <input type="checkbox"/> Cracked _____		
Minor <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low _____ <input type="checkbox"/> Flat _____		
Damage to: <u>Hydraulics hoses crack, leaking and outriggers not operational</u>		
Additional Damage to: _____		
# Of Wheels <u>4</u>	# Of Axles <u>2</u>	# Of Tracks <u>N/A</u>
Dimensions: _____		
Decals: <input checked="" type="checkbox"/> None <input type="checkbox"/> Have been sprayed <input type="checkbox"/> Have been removed <input type="checkbox"/> Impressions remain <input type="checkbox"/> No impressions		
Interior: Color <u>Open Cab</u> <input type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather		
Damage to Seats: <u>Bad Condition</u>		
Damage to Dash/ Floor: <u>No</u>		
Radio: Brand <u>N/A</u> <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD		
<input type="checkbox"/> Cruise Control Power: <input type="checkbox"/> Steering <input type="checkbox"/> Seats <input type="checkbox"/> AC <input checked="" type="checkbox"/> No AC Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown		
Additional Equipment: Manufacturer _____ Model _____		
Serial # _____ Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition		
Description: _____		
Location of Asset: <u>Central Water Plant</u>		
For more information contact: <u>Nickholas Butler</u>		