

Heavy Truck Inspection Form

| Inventory ID: | Asset Number: | Fair Market Value: |
|--|---------------|--------------------|
| Short Description: Year <u>2011</u> Manufacturer <u>KENWORTH</u> Model <u>T800</u> | | |
| VIN: <u>1XKDD49X8BJ278630</u> Title: <input checked="" type="checkbox"/> Clean Title <input type="checkbox"/> Salvage Title <input type="checkbox"/> No Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> Other | | |
| Odometer: <u>691539</u> <input checked="" type="checkbox"/> Miles <input type="checkbox"/> Kilometers <input type="checkbox"/> Hours Odometer Accurate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown | | |
| Long Description: Primary Use for Vehicle: <u>FREIGHT</u> GVW: <u>52000</u> This Vehicle: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost & <input checked="" type="checkbox"/> Is Operable <input type="checkbox"/> Is Not Operable <input type="checkbox"/> For Parts Only Date Removed From Service: <u>01/2024</u> Maintenance Records: <input type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection Engine Manufacture: <u>CUMMINS ISX 15</u> Engine: <u>15</u> L, V <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel This vehicle was maintained every <u>15,000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles # of Axles <u>2</u> Engine Condition: <input checked="" type="checkbox"/> Is operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition Jake Brake: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Engine Repairs needed: <u>TRUCK RAN WHEN PARKED</u> Transmission Manufacture: <u>EATON FULLER</u> <input type="checkbox"/> Automatic <input checked="" type="checkbox"/> Manual <u>10</u> Speed Transmission Condition is: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Unknown Rebuilt Date: _____) Transmission Repairs Needed: _____ | | |
| Exterior: Color <u>WHITE</u> Windows: <input type="checkbox"/> No Cracked Glass <input checked="" type="checkbox"/> Cracked <u>WINDSHIELD</u> Minor: <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low <input type="checkbox"/> Flat _____ Damage to: _____ Additional Damage to: _____ Decals: <input checked="" type="checkbox"/> None <input type="checkbox"/> Have been sprayed <input checked="" type="checkbox"/> Have been Removed & <input checked="" type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions Capacity: _____ Loader: <input type="checkbox"/> Front <input type="checkbox"/> Side Electronic Tarp: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Condition: _____ | | |
| Interior: Color <u>BLACK/GRAY</u> <input checked="" type="checkbox"/> Cloth <input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: _____ Damage to Dash/Floor: _____ Radio: Brand <u>KENWORTH</u> <input checked="" type="checkbox"/> AM <input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input checked="" type="checkbox"/> AM/FM CD <input checked="" type="checkbox"/> Cruise Control <input type="checkbox"/> Tilt Steering <input type="checkbox"/> Remote Mirrors Airbags: <input type="checkbox"/> Driver's Side <input type="checkbox"/> Dual <input checked="" type="checkbox"/> AC <input type="checkbox"/> No AC AC Condition: <input checked="" type="checkbox"/> Cold <input type="checkbox"/> Unknown Power: <input checked="" type="checkbox"/> Windows <input checked="" type="checkbox"/> Doorlocks <input checked="" type="checkbox"/> Steering <input type="checkbox"/> Seats | | |
| Additional Equipment: Manufacturer: <u>UNKNOWN</u> Model: <u>UNKNOWN</u> Serial # _____ Description: <u>WET KIT / HYDRAULIC PTO PUMP</u> Equipment Condition: <input checked="" type="checkbox"/> Is operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition Other Equipment: <u>HEADACHE RACK</u> | | |
| Location of Asset: <u>8700 REMDUNT RD., NLR, AR 72118</u> | | |