Vehicle Inspection Form

Inventory ID:	Asset Number: 1049	Fair Market Value: (DO NOT COMPLETE THIS SECTION)
Short Description: Year 2020 Make DODGE Model DURANGO SSV		
VIN: 1C4SDHFT9LC296653	Title: Clean Title: Court Docum	
Odometer: 59,300 Miles Kilometers Hours Odometer Accurate? Yes No Unknown		
Long Description: This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only Engine- Type: 5.7 L, V 8 Diesel Engine Propane/Natural Gas Gas/Electric Hybrid		
Engine Condition: Runs Needs repair is in unknown condition Repairs needed: fueloung issues - will need to be towed		
This vehicle was maintained every 5,000 Days Hours Miles/Kilometers synthetic oil		
Date Removed from Service: 12 20 24 Maintenance Records: Available Not Available For Inspection		
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition		
Repairs Needed: NONE		
Drivetrain: Wheel Drive 4 Wheel Drive Condition: 9000		
Exterior: Color: Black	Windows: No Crack	ed Glass Cracked windshield window
Minor: Dents Scratches Dings Tire Condition: Good Tread: good #Flat + Hubcaps #		
Major Damage to: NONE		
Additional Damage: NONE		
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color Black Cloth Vinyl Leather Damage to Seats: NONE		
Damage to Dash/Floor: middle console removed		
Radio: Stock or Brand & Model:AM AM/FM AM/FM Cassette AM/FM CD		
AC Condition: Cold Unknown No AC Air Bags: Driver's Side Dual		
Cruise Control Tilt Steering Remote Mirrors Climate Control		
Power: Steering Windows Door Locks Seats		
Additional Equipment: 500+ Light		
Manufacturer Unity Model 504-1 Scrial #		
Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type		
Location of Asset: Malker Police Department		
101 36 Florida Blvd. Walker, UA 70785		
want, it	10100	