

Vehicle Inspection Form

Inventory ID:	Asset Number: <u>55</u>	Fair Market Value:
Short Description: Year <u>2014</u> Make <u>Dodge</u> Model <u>Charger</u>		
VIN: <u>2C3CDXAT4EH148419</u> Title: ☒ Clean Title ☐ Salvage Title ☐ No Title ☐ Court Documents Only ☐ SF97 Form ☐ Other		
Odometer: <u>100,269</u> ☒ Miles ☐ Kilometers ☐ Hours Odometer Accurate? ☐ Yes ☒ No ☐ Unknown		
Long Description: This Vehicle: ☐ Starts ☒ Starts with a Boost & ☒ Runs/Drivable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>5.7 L, V 8</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☐ Runs ☒ Needs repair ☐ is in unknown condition Repairs needed: <u>possible valve chatter or rod knocking</u> This vehicle was maintained every <u>5000</u> ☐ Days ☐ Hours ☒ Miles/Kilometers <u>synthetic oil</u> Date Removed from Service: <u>2-26-25</u> Maintenance Records: ☒ Available ☐ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>NONE</u> Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: <u>good</u>		
Exterior: Color: <u>silver</u> Windows: ☒ No Cracked Glass ☐ Cracked Minor: ☐ Dents ☒ Scratches ☒ Dings Tire Condition: <u>good</u> Tread: <u>good</u> #Flat <u>0</u> Hubcaps # <u>4</u> Major Damage to: <u>NONE</u> Additional Damage: <u>NONE</u> Decals: ☒ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No impressions Emergency equip: ☐ None ☒ Has been removed & ☐ There are holes in the exterior ☒ There are no holes		
Interior: Color <u>dark gray</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>driver seat tear</u> Damage to Dash/Floor: <u>NONE</u> Radio: ☒ Stock or ☐ Brand & Model: ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD AC Condition: ☒ Cold ☐ Unknown ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control <u>dual</u> Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats <u>(driver only)</u>		
Additional Equipment: <u>NONE</u> Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____		
Location of Asset: <u>10136 Florida Blvd., Walker, LA 70785</u>		