Vehicle Inspection Form

For more information contact:
Utility Body: Brand
Manufacturer Model Serial #
Additional Equipment:
Power: Steering Windows Door Locks Seats
☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control
Radio: 🛛 Stock or 🗆 Brand & Model: 🔝 🗀 AM 🗀 AM/FM 🖾 AM/FM Cassette 🗀 AM/FM CD
Ploor: Normal wea
Interior: Color Grey [XCloth Vinyl Leather Damage to Seats: Tear and Assert Seat
Emergency equip: A None Has been removed & There are holes in the exterior There are no holes
P
Additional Damage: Rouf rust print preling
Minor: Dents Dents Dents Dings Tire Condition: New Tread: #Flat Hubcaps #
Exterior: Color: Trees Windows: No Cracked Glass & Cracked Windshield
Drivetrain: X 2 Wheel Drive 4 Wheel Drive Condition: (rece)
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition
Date Removed From Service: 7/1/2025 Maintenance Records: Available Mot Available For Inspection
This webicle was maintained every 2000 Thouse Musical Marine
nn: Runs ∐ Needs repair ∐ is i
Engine-Type: 5.4 L, V_8
This Vehicle: Starts X Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only
Long Description:
Odometer: 5 7 5 7 1 Miles Kilometers Odometer Accurate Y N:
VIN: 1 F B J S 3 1 L J V H B 5 2 2 7 9 Title Restriction: DY XN
Year 1997 Make Ford Model Club Wayson
Asset Number: 10245 Fair Market Value: