

Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year <u>2007</u> Make <u>Ford</u> Model <u>E250</u>		
VIN: <u>1FTNS24L47DA94595</u> Title: ☒ Clean Title ☐ Salvage Title ☐ No Title ☐ Court Documents Only ☐ SF97 Form ☐ Other		
Odometer: <u>48953.1</u> ☒ Miles ☐ Kilometers Hours Odometer Accurate? ☒ Yes ☐ No ☐ Unknown		
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Drivable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: L, V ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: _____		
This vehicle was maintained every <u>3,000</u> ☐ Days ☒ Hours ☒ Miles/Kilometers Date Removed from Service: <u>8-1-2025</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: _____		
Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: _____		
Exterior: Color: <u>White</u> Windows: ☒ No Cracked Glass ☐ Cracked Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: _____ Tread: _____ #Flat Hubcaps # _____ Major Damage to: <u>A lot of rust</u> Additional Damage: <u>Holes rusted in frame rails</u> Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No impressions Emergency equip: ☐ None ☒ Has been removed & ☐ There are holes in the exterior ☐ There are no holes		
Interior: Color <u>Green</u> ☐ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>Small rip in driver seat</u> Damage to Dash/Floor: <u>none seen</u> Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD AC Condition: ☒ Cold ☐ Unknown ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual ☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats		
Additional Equipment: _____		
Manufacturer _____ Model _____ Serial # _____		
☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____		
Location of Asset: _____		