

Bus Inspection Form

Inventory ID	Asset Number	Fair Market Value:
Short Description: Year 2014	Make Chevy	Model Minotaur
VIN: 1GB6G5BG3D1187056		
Mileage/Odometer: 124962	Title: ☒ Clean Title ☐ Salvage Title ☐ Court Documents Only ☐ SF97 Form ☐ No Title ☐ Other	
Mileage/Odometer: 124962	☒ Mi ☐ Km ☐ Hrs Odometer Accurate? ☒ Yes ☐ No ☐ Unknown	
Long Description:		
Primary use for Bus: Public Schools pupil transport # of Passengers: 20		
This vehicle: ☒ Starts with a Boost and ☒ Runs ☐ Does Not Run ☐ For Parts Only		
Engine Manufacturer: GM Engine Type: 6.0 L, V ☒ Gas ☐ Diesel Engine		
This Vehicle was maintained every 3,000 Days ☒ Hours ☒ Miles CNG		
Engine Condition: ☒ Runs ☐ Needs repair ☐ Is in Unknown Condition		
Repairs needed: _____		
Date Removed From Service: _____ Maintenance Records: ☐ Available ☒ Not Available		
Transmission Manufacturer: GM ☒ Automatic ☐ Manual _____ Speed		
Transmission Condition is: ☒ Operable ☐ Needs Repair ☐ Unknown Rebuilt (Date: _____)		
Repairs Needed: _____		
Date Removed From Service: _____ Maintenance Records: ☐ Available ☒ Not Available For Inspection		
Exterior Description:		
Color: yellow Windows: ☒ No Cracked Glass ☐ Cracked _____		
Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: Low _____ Flat _____		
Damage to: _____		
Additional Damage to: _____		
Decals: ☐ None ☐ Have been Sprayed Over ☒ Have been removed & ☐ Impressions Remain ☐ No Impressions		
Other Exterior Information: _____		
Interior Description:		
Color blue ☒ Vinyl ☐ Cloth ☐ Leather		
Damage to Seats: _____		
Damage to Dash/Floor: _____		
Radio: Brand _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD		
Air Conditioning: ☒ Yes ☐ No AC Operating Condition: ☒ Cold ☐ Unknown		
Other Interior Information/Options: _____		
Other Equipment: Description _____		
Manufacturer _____ Model _____ Serial # _____		
Location of Asset: _____		