

Bus Inspection Form

Inventory ID		Asset Number 112	Fair Market Value:
Short Description: Year 2014 Make Chevy Model Minotaur			
VIN: 1GB6G5BG4D1182917	Title: ☒ Clean Title ☐ Salvage Title ☐ Court Documents Only		
Mileage/Odometer: 149111	☒ SF97 Form ☐ No Title Other _____ ☒ Mi Km Hrs Odometer Accurate? ☒ Yes ☐ No Unknown		
Long Description: Primary use for Bus: Public Schools pupil transport # of Passengers: 20			
This vehicle: ☒ Starts with a Boost and ☒ Runs Does Not Run ☐ For Parts Only			
Engine Manufacturer: GM	Engine Type: 6.0 L V ☒ Gas Diesel Engine CNG		
This Vehicle was maintained every 3,000 Days Hours ☒ Miles			
Engine Condition: ☒ Runs Needs repair Is in Unknown Condition			
Repairs needed: _____			
Date Removed From Service: _____ Maintenance Records: ☐ Available ☒ Not Available			
Transmission Manufacture: GM	☒ Automatic Manual Speed		
Transmission Condition is: ☒ Operable Needs Repair Unknown Rebuilt (Date: _____)			
Repairs Needed: _____			
Date Removed From Service: _____ Maintenance Records: ☐ Available ☒ Not Available For Inspection			
Exterior Description:			
Color: yellow Windows: ☒ No Cracked Glass ☐ Cracked			
Minor: ☐ Dents Scratches Dings Tire Condition: Low Flat Damage to: _____			
Additional Damage to: _____			
Decals: ☐ None Have been Sprayed Over ☒ Have been removed & Impressions Remain No Impressions			
Other Exterior Information: _____			
Interior Description:			
Color blue ☒ Vinyl Cloth Leather			
Damage to Seats: _____			
Damage to Dash/Floor: _____			
Radio: Brand AM FM AM/FM Cassette AM/FM CD			
Air Conditioning: ☒ Yes No AC Operating Condition: Cold Unknown			
Other Interior Information/Options: _____			
Other Equipment: Description _____			
Manufacturer Model Serial # _____			
Location of Asset: _____			