

Bus Inspection Form

Inventory ID	Asset Number	Fair Market Value:
	153	

Short Description:
 Year 2014 _____ Make Chevy _____ Model Minotaur _____

VIN: 1GBG5BG6D1185978
 Title: ☒ Clean Title ☐ Salvage Title ☐ Court Documents Only
☐ SF97 Form ☐ No Title ☐ Other

Mileage/Odometer: 128551 ☒ Mi ☐ Km ☐ Hrs Odometer Accurate? ☒ Yes ☐ No ☐ Unknown

Long Description:

Primary use for Bus: Public Schools pupil transport # of Passengers: 20

This vehicle: ☒ Starts ☐ Starts with a Boost and ☒ Runs ☐ Does Not Run ☐ For Parts Only

Engine Manufacturer: GM Engine Type: 6.0 L, V ☒ Gas ☐ Diesel Engine

This Vehicle was maintained every 3,000 ☐ Days ☒ Hours ☒ Miles CNG

Engine Condition: ☒ Runs ☐ Needs repair ☐ Is in Unknown Condition

Repairs needed: _____

Date Removed From Service: _____ Maintenance Records: ☐ Available ☒ Not Available

Transmission Manufacturer: GM ☒ Automatic ☐ Manual _____ Speed

Transmission Condition is: ☒ Operable ☐ Needs Repair ☐ Unknown Rebuilt (Date: _____)

Repairs Needed: _____

Date Removed From Service: _____ Maintenance Records: ☐ Available ☒ Not Available For Inspection

Exterior Description:

Color: yellow Windows: ☒ No Cracked Glass ☐ Cracked _____

Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: Low _____ Flat _____

Damage to: _____

Additional Damage to: _____

Decals: ☐ None ☐ Have been Sprayed Over ☒ Have been removed & ☐ Impressions Remain ☐ No Impressions

Other Exterior Information: _____

Interior Description:

Color blue ☒ Vinyl ☐ Cloth ☐ Leather

Damage to Seats: _____

Damage to Dash/Floor: _____

Radio: Brand _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

Air Conditioning: ☒ Yes ☐ No AC Operating Condition: ☒ Cold ☐ Unknown

Other Interior Information/Options: _____

Other Equipment: Description _____

Manufacturer _____ Model _____ Serial # _____

Location of Asset: _____