

2014 Dodge Grand Caravan

****See pictures for visuals on Exterior and Interior Notes****

Exterior Notes:

- **Paint is bubbling up and flaking off of aluminum hood**
- **One headlight assembly looks new while other is old and cloudy**
- **Rust is starting in both rear wheel wells**
- **Small scuff in rear fascia**
- **Paint is cracked on passenger side sliding door**
- **Trim is loose on passenger side front door**

Interior Notes:

- **No cracks, rips, or holes**
- **No backup camera**
- **Has Stow-n-Go fold away rear seating**