

2013 Toyota Tacoma

****See pictures for visuals on Exterior and Interior Notes****

Exterior Notes:

- A couple rock chips in hood and one in leading edge of roof
- A couple of dings in roof
- Ding by fuel filler door
- A few scratches here and there
- Could use a thorough cleaning
- Paint is peeling on B-pillar of both front doors
- Has a Truxedo tonneau cover

Interior Notes:

- No rips, cracks, or holes
- No backup camera
- Nice interior