

GovDeals Heavy Truck Inspection Form

Inventory ID: <u>094890</u>	Asset Number:	Fair Market Value:																	
Short Description:																			
Year <u>2009</u>	Manufacturer <u>Freightliner</u>	Model <u>M2-106</u>																	
VIN: <table border="1" style="display: inline-table; text-align: center; width: 100%;"> <tr> <td>1</td><td>F</td><td>V</td><td>A</td><td>C</td><td>Y</td><td>D</td><td>J</td><td>6</td><td>9</td><td>H</td><td>A</td><td>H</td><td>7</td><td>4</td><td>8</td><td>5</td> </tr> </table>			1	F	V	A	C	Y	D	J	6	9	H	A	H	7	4	8	5
1	F	V	A	C	Y	D	J	6	9	H	A	H	7	4	8	5			
Mileage/Odometer: <table border="1" style="display: inline-table; text-align: center; width: 100%;"> <tr> <td>1</td><td>5</td><td>7</td><td>8</td><td>9</td><td>1</td> </tr> </table>		1	5	7	8	9	1	Odometer Accurate: <input checked="" type="checkbox"/> Y <input type="checkbox"/> N: <u>dash Replaced at 81285 miles</u> <u>Miles Unknown</u>											
1	5	7	8	9	1														
Long Description: Primary Use for Vehicle: <u>Delivery operations</u> GVW: <u>36,200</u>																			
This Vehicle: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost & <input checked="" type="checkbox"/> Is Operable <input type="checkbox"/> Is Not Operable <input type="checkbox"/> For Parts Only																			
Date Removed From Service: <u>12/3/25</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection																			
Engine Manufacture: <u>Mercedes Benz</u> Engine: <u>7.2L, V</u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel																			
This vehicle was maintained every <u>4,000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles # of Axles <u>2</u>																			
Engine Condition: <input type="checkbox"/> Is operable <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/> Is in Unknown Condition Jake Brake: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No																			
Engine Repairs needed: <u>unknown</u>																			
Transmission Manufacture: <u>Allison</u> <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual <u>Speed</u>																			
Transmission Condition is: <input type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input checked="" type="checkbox"/> Unknown <input type="checkbox"/> Rebuilt (Date: _____)																			
Transmission Repairs Needed: <u>unknown</u>																			
Exterior: Color <u>Navy Blue</u> Windows: <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked _____																			
Minor: <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <input checked="" type="checkbox"/> Low <input type="checkbox"/> Flat _____																			
Damage to: _____																			
Additional Damage to: _____																			
Decals: <input type="checkbox"/> None <input type="checkbox"/> Have been sprayed <input checked="" type="checkbox"/> Have been Removed & <input checked="" type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions																			
Capacity: <u>N/A</u> Loader: <input type="checkbox"/> Front <input type="checkbox"/> Side Electronic Tarp: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Condition: _____																			
Interior: Color <u>Gray</u> <input type="checkbox"/> Cloth <input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Leather																			
Damage to Seats: <u>Yes Stains/Tears</u>																			
Damage to Dash/Floor: <u>Yes Stains/Tears</u>																			
Radio: Brand <u>Delphi</u> <input type="checkbox"/> AM <input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD																			
<input checked="" type="checkbox"/> Cruise Control <input type="checkbox"/> Tilt Steering <input type="checkbox"/> Remote Mirrors Airbags: <input type="checkbox"/> Driver's Side <input type="checkbox"/> Dual																			
<input checked="" type="checkbox"/> AC <input type="checkbox"/> No AC AC Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown Power: <input type="checkbox"/> Windows <input type="checkbox"/> Doorlocks <input checked="" type="checkbox"/> Steering <input type="checkbox"/> Seats																			
Additional Equipment: Manufacturer: <u>Morgan Body</u> Model: <u>GVFDO9116096</u>																			
Serial # <u>MPA08VBO2799003</u> Description: <u>Box/van Body w/ Rear Rollup door</u>																			
Equipment Condition: <input checked="" type="checkbox"/> Is operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition																			
Other Equipment: _____																			
Location of Asset: <u>16700 Crabbs Branch Way Derwood MD 20855</u>																			
For more information contact: _____																			