

Bus Inspection Form

✓ 8-25-25

| | | |
|---|---------------------------|---------------------------|
| Inventory ID B-358 | Asset Number B-358 | Fair Market Value: |
| Short Description: Year <u>2007</u> Make <u>International</u> Model <u>CE Series</u> | | |
| VIN: 4 D R B U A F P 9 7 B 3 9 5 1 3 5 | | |
| Mileage/Odometer: 1 3 3 0 6 6 Odometer Accurate <input checked="" type="checkbox"/> Y <input type="checkbox"/> N: _____ | | |
| Long Description: Primary use for Bus: <u>Transport Students</u> # of Passengers: <u>71</u> This vehicle: <input type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost and <input type="checkbox"/> Runs <input checked="" type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only Engine Manufacture: <u>International VT365</u> Engine Type: <u>6.0</u> L, V <u>8</u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine This Vehicle was maintained every <u>8000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles Engine Condition: <input type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/> Is in Unknown Condition Repairs needed: <u>IDM Relay Shorted out/ Low crank Oil Pressure</u> Date Removed From Service: <u>07/2024</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available Transmission Manufacture: <u>Allison</u> <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual _____ Speed Transmission Condition is: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Unknown <input type="checkbox"/> Rebuilt (Date: _____) Repairs Needed: <u>Unknown</u> Date Removed From Service: <u>07/2024</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection | | |
| Exterior Description: Color: <u>Yellow</u> Windows: <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked _____ Minor: <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low _____ <input type="checkbox"/> Flat _____ Damage to: _____ Additional Damage to: _____ Decals: <input type="checkbox"/> None <input type="checkbox"/> Have been Sprayed Over <input checked="" type="checkbox"/> Have been removed & <input checked="" type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions Other Exterior Information: _____ | | |
| Interior Description: Color <u>Grey</u> <input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Cloth <input type="checkbox"/> Leather Damage to Seats: <u>Unknown</u> Damage to Dash/Floor: <u>Unknown</u> Radio: Brand <u>N/A</u> <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD Air Conditioning: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No AC Operating Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown Other Interior Information/Options: _____ | | |
| Other Equipment: Description _____ Manufacturer _____ Model _____ Serial # _____ | | |
| Location of Asset: <u>(LCM Bus Lot) 3203 Wilson Mill Road, Lake Cormorant, Mississippi, 38641</u> For more information contact: _____ | | |