

# Bus Inspection Form

BUS-59

8-21-25

Inventory ID **BUS-59**

Asset Number **BUS-59**

Fair Market Value:

**Short Description:**

Year **2000**

Make **International**

Model **Blue Bird 3800**

VIN: **1HVBABP1YH295555**

Title Restriction: ☐ Y ☒ N

Mileage/Odometer: **212194**

Odometer Accurate ☒ Y ☐ N:

**Long Description:**

Primary use for Bus: **Transport Students**

# of Passengers: **71**

This vehicle: ☐ Starts ☒ Starts with a Boost and ☐ Runs ☐ Does Not Run

☐ For Parts Only

Engine Manufacture: **International 444E**

Engine Type: **7.3**

L, V **8**

☐ Gas ☒ Diesel Engine

This Vehicle was maintained every **8000**

☐ Days ☐ Hours ☒ Miles

Engine Condition: ☒ Runs ☐ Needs repair ☐ Is in Unknown Condition

Repairs needed: **Unknown**

Date Removed From Service: **11/2024**

Maintenance Records: ☐ Available ☒ Not Available

Transmission Manufacture: **Allison**

☒ Automatic ☐ Manual **4** Speed

Transmission Condition is: ☒ Operable ☐ Needs Repair ☐ Unknown ☐ Rebuilt (Date: )

Repairs Needed: **Unknown**

Date Removed From Service: **11/2024**

Maintenance Records: ☐ Available ☒ Not Available For Inspection

**Exterior Description:**

Color: **Yellow**

Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☒ Dents ☒ Scratches ☒ Dings

Tire Condition: ☐ Low ☐ Flat

Damage to:

Additional Damage to:

Decals: ☐ None ☐ Have been Sprayed Over ☒ Have been removed & ☒ Impressions Remain ☐ No Impressions

Other Exterior Information:

**Interior Description:**

Color **Brown**

☒ Vinyl ☐ Cloth ☐ Leather

Damage to Seats: **Unknown**

Damage to Dash/Floor: **Floors Rusted Out**

Radio: Brand **N/A**

☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

Air Conditioning: ☐ Yes ☒ No

AC Operating Condition: ☐ Cold ☐ Unknown

Other Interior Information/Options:

Other Equipment: Description

Manufacturer

Model

Serial #

Location of Asset: **(LCM Bus Lot) 3203 Wilson Mill Rd, Lake Cormorant, Mississippi, 38641**

For more information contact: