

Bus Inspection Form

#889

✓ 8-21-25

Inventory ID B 472	Asset Number B 472	Fair Market Value:
<u>Short Description:</u> Year 2011	Make International	Model _____
VIN: 4 D R A P S K K 2 C B 6 1 1 2 2 6		Title Restriction: <input type="checkbox"/> Y <input checked="" type="checkbox"/> N
Mileage/Odometer: 1 5 4 9 1 7 Odometer Accurate <input type="checkbox"/> Y <input type="checkbox"/> N: _____		
<u>Long Description:</u>		
Primary use for Bus: Transport Students		# of Passengers: 30
This vehicle: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost and <input type="checkbox"/> Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only		
Engine Manufacture: International Maxxforce 7 Engine Type: 6.4 L, V8 <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine		
This Vehicle was maintained every 8000 <input type="checkbox"/> Days <input type="checkbox"/> Hours <input type="checkbox"/> Miles		
Engine Condition: <input type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition		
Repairs needed: Will Start, But Low Fuel Rail Pressure, Low Oil Pressure once up to Temp.		
Date Removed From Service: 05/2025		Maintenance Records: <input type="checkbox"/> Available <input type="checkbox"/> Not Available
Transmission Manufacture: Allison <input type="checkbox"/> Automatic <input type="checkbox"/> Manual 6 Speed		
Transmission Condition is: <input type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Unknown <input type="checkbox"/> Rebuilt (Date: _____)		
Repairs Needed: Unknown		
Date Removed From Service: 05/2025		Maintenance Records: <input type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection
<u>Exterior Description:</u>		
Color: Yellow Windows: <input type="checkbox"/> No Cracked Glass <input checked="" type="checkbox"/> Cracked _____		
Minor: <input type="checkbox"/> Dents <input type="checkbox"/> Scratches <input type="checkbox"/> Dings		Tire Condition: <input type="checkbox"/> Low <input type="checkbox"/> Flat _____
Damage to: _____		
Additional Damage to: _____		
Decals: <input type="checkbox"/> None <input type="checkbox"/> Have been Sprayed Over <input checked="" type="checkbox"/> Have been removed & <input type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions		
Other Exterior Information: _____		
<u>Interior Description:</u>		
Color Grey <input type="checkbox"/> Vinyl <input type="checkbox"/> Cloth <input type="checkbox"/> Leather		
Damage to Seats: Unknown		
Damage to Dash/Floor: Unknown		
Radio: Brand _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD		
Air Conditioning: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No AC Operating Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown		
Other Interior Information/Options: _____		
Other Equipment: Description Wheel Chair Lift		
Manufacturer Braun Model Mellinium Serial # _____		
Location of Asset: _____		
For more information contact: (Shop Lot) 2211 Central Pkwy, Seuthaven, MS 38672 Q DES		