Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description:		
Year 2002 Make Cheurolet Model Silverado 2500		
VIN: <u>IGBHK24 U22E 104716</u> Title: UClean Title Salvage Title No Title Court Documents Only SF97 Form Other		
Odometer: 229,177 Miles Kilometers Hours Odometer Accurate? Yes No Unknown		
Long Description:		
This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only		
Engine- Type: 6.0 L, V S Diesel Engine Propane/Natural Gas Gas/Electric Hybrid		
Engine Condition: Runs Needs repair is in unknown condition		
Repairs needed: Engine Starts But Very Low Compression		
This vehicle was maintained every 1 months Days Hours Miles/Kilometers		
Date Removed from Service:Maintenance Records: Available Not Available For Inspection		
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition		
Repairs Needed:		
Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition:		
Exterior: Color: White Windows: No Cracked Glass Cracked		
Minor: Dents Scratches Dings Tire Condition: 50 % Tread: #Flat Hubcaps #		
Major Damage to:		
Additional Damage: Rust On Cah		
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions		
Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color Grey Cloth Vinyl Leather		
Damage to Seats:		
Damage to Dash/Floor:		
Radio: Stock or Brand & Model: AM AM/FM AM/FM Cassette AM/FM CD		
AC Condition: Cold Unknown No AC Air Bags: Driver's Side Dual		
Cruise Control Tilt Steering Remote Mirrors Climate Control		
Power: Steering Windows Door Locks Seats		
Additional Equipment:		
Manufacturer Model Serial #		
Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type		
Location of Asset:		