

Vehicle Inspection Form

| | | |
|--|----------------------|---------------------------|
| Inventory ID: 000435SG | Asset Number: | Fair Market Value: |
| Short Description: Year <u>2008</u> Make <u>Dodge</u> Model <u>Durango</u> | | |
| VIN: <u>1D8HB38N68F124086</u> Title: <input checked="" type="checkbox"/> Clean Title <input type="checkbox"/> Salvage Title <input type="checkbox"/> No Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> Other | | |
| Odometer: <u>189,034</u> <input checked="" type="checkbox"/> Miles <input type="checkbox"/> Kilometers <input type="checkbox"/> Hours Odometer Accurate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown | | |
| Long Description: | | |
| This Vehicle: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost & <input checked="" type="checkbox"/> Runs/Drivable <input type="checkbox"/> Engine Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only | | |
| Engine- Type: <u>4.7</u> L, V <u>8</u> <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine <input type="checkbox"/> Propane/Natural Gas <input type="checkbox"/> Gas/Electric Hybrid | | |
| Engine Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> is in unknown condition | | |
| Repairs needed: <u>Needs a new battery, Emissions tag is missing</u> | | |
| This vehicle was maintained every <u>6 MONTHS</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input type="checkbox"/> Miles/Kilometers | | |
| Date Removed from Service: <u>10/01/2024</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection | | |
| Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual ___ Speed Condition: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is Unknown Condition | | |
| Repairs Needed: <u>None noted</u> | | |
| Drivetrain: <input type="checkbox"/> 2 Wheel Drive <input type="checkbox"/> 4 Wheel Drive Condition: <u>AWD (Good)</u> | | |
| Exterior: Color: <u>Silver</u> Windows: <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked | | |
| Minor: <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <u>Fair</u> Tread: <u>8/32</u> #Flat _____ Hubcaps # <u>4</u> | | |
| Major Damage to: <u>Clear coat/Paint is peeling</u> | | |
| Additional Damage: <u>RH rear door is scraped</u> | | |
| Decals: <input type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed or <input checked="" type="checkbox"/> Have been Removed & <input checked="" type="checkbox"/> Impressions Remain <input type="checkbox"/> No impressions | | |
| Emergency equip: <input checked="" type="checkbox"/> None <input type="checkbox"/> Has been removed & <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes | | |
| Interior: Color <u>Grey</u> <input checked="" type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather | | |
| Damage to Seats: <u>Stained/Dirty, Interior has a bad smell (possibly rodent)</u> | | |
| Damage to Dash/Floor: <u>Stained/Dirty</u> | | |
| Radio: <input checked="" type="checkbox"/> Stock or <input type="checkbox"/> Brand & Model: _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input checked="" type="checkbox"/> AM/FM CD | | |
| AC Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown <input type="checkbox"/> No AC Air Bags: <input type="checkbox"/> Driver's Side <input checked="" type="checkbox"/> Dual | | |
| <input checked="" type="checkbox"/> Cruise Control <input checked="" type="checkbox"/> Tilt Steering <input checked="" type="checkbox"/> Remote Mirrors <input checked="" type="checkbox"/> Climate Control | | |
| Power: <input checked="" type="checkbox"/> Steering <input checked="" type="checkbox"/> Windows <input checked="" type="checkbox"/> Door Locks <input type="checkbox"/> Seats | | |
| Additional Equipment: _____ | | |
| Manufacturer _____ Model _____ Serial # _____ | | |
| <input type="checkbox"/> Tool Box <input type="checkbox"/> Light Bar <input type="checkbox"/> Ladder Rack <input type="checkbox"/> Utility Body: Brand _____ <input type="checkbox"/> Hitch: Type _____ | | |
| Location of Asset: <u>1990 Siringo Rd. Santa Fe, NM 87505</u> | | |