

Vehicle Inspection Form

Inventory ID: 001666SG	Asset Number:	Fair Market Value:																	
Short Description: Year <u>2010</u> Make <u>FORD</u> Model <u>F250 XL 2WD SUPER DUTY</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 400px;"> <tr> <td>1</td><td>F</td><td>T</td><td>S</td><td>F</td><td>2</td><td>A</td><td>R</td><td>X</td><td>A</td><td>E</td><td>B</td><td>1</td><td>7</td><td>3</td><td>1</td><td>5</td> </tr> </table> Title Restriction: ☐ Y ☒ N			1	F	T	S	F	2	A	R	X	A	E	B	1	7	3	1	5
1	F	T	S	F	2	A	R	X	A	E	B	1	7	3	1	5			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 150px;"> <tr> <td>9</td><td>2</td><td>3</td><td>1</td><td>5</td><td></td> </tr> </table> ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____			9	2	3	1	5												
9	2	3	1	5															
Long Description: This Vehicle: ☐ Starts ☒ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>6.4 L, V 8</u> ☒ Gas ☒ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☐ Runs ☒ Needs repair ☐ is in unknown condition Repairs needed: <u>REMOVED FROM SERVICE DUE TO AGE/POOR CONDITION/NEEDS TURBO</u> This vehicle was maintained every <u>6 MONTHS</u> ☐ Days ☐ Hours ☐ Miles Date Removed From Service: <u>01/31/2023</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual <u>Speed</u> Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>NONE NOTED</u> Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: <u>Bad</u>																			
Exterior: Color: <u>SILVER</u> Windows: ☒ No Cracked Glass ☐ Cracked _____ Minor: ☐ Dents ☒ Scratches ☒ Dings Tire Condition: <u>POOR</u> Tread: <u>2 /32</u> #Flat _____ Hubcaps # _____ Major Damage to: <u>PAINT PEELING ON AREAS OF TRUCK</u> Additional Damage: <u>TAILGATE MISSING TOP TRIM PIECE</u> Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>Beige</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>DRIVERSIDE SEAT TORN & SEAT DIRTY</u> Damage to Dash/Floor: <u>HEADLINER IS COMING UNGLUED IN AREAS. DASH AND FLOOR DIRTY</u> Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD ☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☒ Climate Control Power: ☒ Steering ☐ Windows ☐ Door Locks ☐ Seats																			
Additional Equipment: <u>N/A</u> Manufacturer <u>N/A</u> Model <u>N/A</u> Serial # <u>N/A</u> ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand <u>N/A</u> ☐ Hitch: Type <u>N/A</u>																			
Location of Asset: _____ For more information contact: _____ Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			