Vehicle Inspection Form

Inventory ID: 004410SG	**Asset Number:**	**Fair Market Value:**

Short Description:
Year 2014   Make Chevy   Model Express 3500

VIN: 1GCWGGCG1E1197950   **Title:** ☑ Clean Title ☐ Salvage Title ☐ No Title
☐ Court Documents Only ☐ SF97 Form ☐ Other

Odometer: 106,409 ☑ Miles ☐ Kilometers ☐ Hours **Odometer Accurate?** ☑ Yes ☐ No ☐ Unknown

Long Description:
This Vehicle: ☐ Starts ☑ Starts with a Boost & ☑ Runs/Drivable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 6.0 L, V 8   ☑ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☑ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed: None Noted

This vehicle was maintained every 6 MONTHS ☐ Days ☐ Hours ☐ Miles/Kilometers

Date Removed from Service: 10/01/2024   Maintenance Records: ☐ Available ☑ Not Available For Inspection

Transmission: ☑ Automatic ☐ Manual ___ Speed   Condition: ☑ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: Service stabilitrak message is on

Drivetrain: ☑ 2 Wheel Drive ☐ 4 Wheel Drive   Condition: Fair

Exterior: Color: Silver   Windows: ☑ No Cracked Glass ☐ Cracked

Minor: ☐ Dents ☑ Scratches ☑ Dings   Tire Condition: Bad   Tread: 4/32   #Flat ___   Hubcaps # 4

Major Damage to: Rear door is bent

Additional Damage: Wheel chair lift is inoperable

Decals: ☐ None ☐ Have Been Sprayed or ☑ Have been Removed & ☑ Impressions Remain ☐ No impressions

Emergency equip: ☑ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color Grey   ☑ Cloth ☐ Vinyl ☐ Leather

Damage to Seats: Stained/Dirty

Damage to Dash/Floor: Stained/Dirty, stand up height is about 5 ft 9 inches

Radio: ☑ Stock or ☐ Brand & Model: _____   ☐ AM ☑ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☐ Cold ☐ Unknown ☐ No AC   Air Bags: ☐ Driver's Side ☑ Dual

☑ Cruise Control ☑ Tilt Steering ☑ Remote Mirrors ☑ Climate Control

Power: ☑ Steering ☐ Windows ☐ Door Locks ☐ Seats

Additional Equipment: _____

Manufacturer _____ Model _____ Serial # _____

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand_____ ☐ Hitch: Type_____

Location of Asset: 1990 Siringo Rd. Santa Fe, NM 87505