Vehicle Inspection Form

Inventory ID: G48285	Asset Number:	Fair Market Value:
Short Description: Make_DODGE Year 2001		
VIN: 1 B 7 K F 2 3 W 5 1 J 6 1 5 5 9 3 Title Restriction: Title Restritereeeeeeeeeeeeeeeeeeeeeeeee		
Long Description: This Vehicle: Starts Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only Engine- Type: 8.0 L, V 10 Image: Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid Engine Condition: Runs Needs repair is in unknown condition Repairs needed: NOTES STATE REMOVED FROM SERVICE DUE TO AGE/MILEAGE This vehicle was maintained every 6 MONTHS Days Hours Miles Date Removed From Service: 1/10/2023 Maintenance Records: Available Not Available For Inspection Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition Repairs Needed: NONE NOTED Speed Condition: Operable Needs repair Is Unknown Condition		
Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition: GOOD Exterior: Color: SILVER Windows: No Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: POOR Tread: 3 /32 #Flat Hubcaps # Major Damage to: CLEARCOAT PEELING THROUGHOUT VEHICLE Additional Damage: PAINT PEELING THROUGHOUT VEHICLE Decals: None Have been Removed & Impressions Remain No Impressions Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color GRAY Image Cloth Vinyl Leather Damage to Seats: DRIVERS SEAT TORN. SEATS ARE DIRTY Damage to Dash/Floor: DASH IS COMPLETELY BROKEN. HEADLINER TORN/COMING UNGLUED. Radio: Image Stock or Image Brand & Model: Image And And/FM Image And/FM Cassette Radio: Image Condition: Image Cold Image And/FM Image And/FM Cassette Image And/FM Cold Image Condition: Image Cold Image And/FM Image And/FM Image And/FM Cassette Image And/FM Cold Image Condition: Image Cold Image And/FM Im		
Additional Equipment:		