Vehicle Inspection Form

Inventory ID: 001259SG	Asset Number:	Fair Market Value:
Short Description: Year 2001 Make CHEVY Model MALIBU		
VIN: 1 G 1 Z G 5 7 K 2 9 4 2 3 6 2 8 3 Title Restriction:		
Long Description: This Vehicle: □ Starts ■ Starts with a Boost & ■ Runs/Driveable □ Engine Runs □ Does Not Run □ For Parts Only Engine- Type: 3.5 L, V 6 ■ Gas □ Diesel Engine □ Propane/Natural Gas □ Gas/Electric Hybrid Engine Condition: □ Runs □ Needs repair □ is in unknown condition Repairs needed: NOTES STATE THAT VEHICLE WAS REMOVED DUE TO AGE/MILEAGE This vehicle was maintained every 6 MONTHS □ Days □ Hours □ Miles Date Removed From Service: 7/30/2024 ■ Maintenance Records: □ Available ■ Not Available For Inspection Transmission: ■ Automatic □ Manual _ Speed Condition: ■ Operable □ Needs repair □ Is Unknown Condition Repairs Needed: NONE NOTED		
Drivetrain: ■ 2 Wheel Drive □ 4 Wheel Drive Condition: GOOD Exterior: Color: GREEN Windows: ■ No Cracked Glass □ Cracked		
Interior: Color GRAY		
Additional Equipment: Manufacturer Model Serial # Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type Location of Asset: For more information contact:		
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		