Vehicle Inspection Form

Inventory ID: 004894SG	Asset Number:	Fair Market Value:
Short Description: Year 2015 Make CHEVY Model SILVERADO		
VIN: 1 G C 2 K U E G 2 F Z 5 3 1 6 4 2 Title Restriction: Odometer: 2 0 8 3 4 2 Miles Kilometers Odometer Accurate Y N:		
Long Description:		
This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only		
Engine- Type: 6.0 _{L, V_8} ■ Gas □ Diesel Engine □ Propane/Natural Gas □ Gas/Electric Hybrid		
Engine Condition: Runs Needs repair is in unknown condition		
Repairs needed: NOTES STATE REMOVED FROM SERVICE DUE TO AGE/MILEAGE		
This vehicle was maintained every 6 MONTHS Days Days Miles		
Date Removed From Service: 6/8/2022 Maintenance Records: ☐ Available ■ Not Available For Inspection		
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition		
Repairs Needed: NOTES STATE NEEDS TRANSMISSION		
<u>Drivetrain</u> : ☐ 2 Wheel Drive ■ 4 Wheel Drive Condition: FAIR		
Exterior: Color: SILVER Windows: No Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: POOR Tread: 3 /32 #Flat Hubcaps #_ Major Damage to: N/A		
Additional Damage: N/A		
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color GRAY □ Cloth □ Vinyl □ Leather Damage to Seats: STAINED/DIRTY Damage to Dash/Floor: STAINED/DIRTY		
Radio: ■ Stock or □ Brand & Model: □ AM ■ AM/FM □ AM/FM Cassette □ AM/FM CD		
■ AC (Condition: ■ Cold □ Unknown) □ No AC Air Bags: □ Driver's Side ■ Dual		
■ Cruise Control ■ Tilt Steering ■ Remote Mirrors ■ Climate Control		
Power: Steering Windows Door Locks Seats		
Additional Equipment:		
Manufacturer Moc	lel Serial #	
☐ Tool Box ☐ Light Bar ☐ Ladder Rac	k Utility Body: Brand	
Location of Asset: For more information contact: Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		