

Vehicle Inspection Form

Inventory ID: G70701	Asset Number:	Fair Market Value:																	
Short Description: Year <u>2007</u> Make <u>HONDA</u> Model <u>ACCORD HYBRID</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 300px;"> <tr> <td>J</td><td>H</td><td>M</td><td>C</td><td>N</td><td>3</td><td>6</td><td>4</td><td>8</td><td>7</td><td>C</td><td>0</td><td>0</td><td>3</td><td>2</td><td>3</td><td>1</td> </tr> </table> Title Restriction: ☐ Y ☒ N			J	H	M	C	N	3	6	4	8	7	C	0	0	3	2	3	1
J	H	M	C	N	3	6	4	8	7	C	0	0	3	2	3	1			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 100px;"> <tr> <td>1</td><td>3</td><td>4</td><td>4</td><td>5</td><td>6</td> </tr> </table> ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____			1	3	4	4	5	6											
1	3	4	4	5	6														
Long Description: This Vehicle: ☐ Starts ☒ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>3.0</u> L, V <u>6</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☒ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>REMOVED FROM SERVICE DUE TO AGE/MILEAGE</u> This vehicle was maintained every <u>6 MONTHS</u> ☐ Days ☐ Hours ☐ Miles Date Removed From Service: <u>10/6/2023</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual _____ Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>NONE NOTED</u> Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: <u>Good</u>																			
Exterior: Color: <u>BLUE</u> Windows: ☐ No Cracked Glass ☒ Cracked _____ Minor: ☐ Dents ☒ Scratches ☒ Dings Tire Condition: <u>FAIR</u> Tread: <u>4/32</u> #Flat _____ Hubcaps # _____ Major Damage to: <u>WINDSHIELD CRACKED</u> Additional Damage: <u>PAINT FAIDING/CLEARCOAT PEELIG THROUGHOUT VEHICLE</u> Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>GRAY</u> ☐ Cloth ☒ Vinyl ☐ Leather Damage to Seats: <u>SEATS DIRTY</u> Damage to Dash/Floor: <u>FLOORS DIRTY. RADIO NOT WORKING</u> Radio: ☒ Stock or ☐ Brand & Model: <u>N/A</u> ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD ☒ AC (Condition: ☐ Cold ☒ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats																			
Additional Equipment: <u>N/A</u> Manufacturer <u>N/A</u> Model <u>N/A</u> Serial # <u>N/A</u> ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____																			
Location of Asset: _____ For more information contact: _____ Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			