

Vehicle Inspection Form

Inventory ID: G71353	Asset Number:	Fair Market Value:																	
Short Description: Year <u>2007</u> Make <u>DODGE</u> Model <u>DURANGO</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 250px;"> <tr><td>1</td><td>D</td><td>8</td><td>H</td><td>D</td><td>3</td><td>8</td><td>P</td><td>8</td><td>7</td><td>F</td><td>5</td><td>5</td><td>8</td><td>3</td><td>2</td><td>6</td></tr> </table> Title Restriction: ☐ Y ☒ N			1	D	8	H	D	3	8	P	8	7	F	5	5	8	3	2	6
1	D	8	H	D	3	8	P	8	7	F	5	5	8	3	2	6			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 100px;"> <tr><td>1</td><td>4</td><td>2</td><td>3</td><td>0</td><td>7</td></tr> </table> ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____			1	4	2	3	0	7											
1	4	2	3	0	7														
Long Description: This Vehicle: ☐ Starts ☒ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>4.7</u> L, V <u>8</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>REMOVED FROM SERVICE DUE TO AGE/MILEAGE</u> This vehicle was maintained every <u>6 MONTHS</u> ☐ Days ☐ Hours ☐ Miles Date Removed From Service: <u>9/22/2022</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>NONE NOTED</u> Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: <u>Good</u>																			
Exterior: Color: <u>SILVER</u> Windows: ☒ No Cracked Glass ☐ Cracked _____ Minor: ☐ Dents ☒ Scratches ☒ Dings Tire Condition: <u>POOR</u> Tread: <u>2 /32</u> #Flat____ Hubcaps #____ Major Damage to: <u>NONE</u> Additional Damage: <u>NONE</u> Decals: ☐ None ☐ Have Been Sprayed <u>or</u> ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>GRAY</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>Stained/Dirty</u> Damage to Dash/Floor: <u>DIRTY</u> Radio: ☒ Stock <u>or</u> ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD ☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats																			
Additional Equipment: <u>N/A</u> Manufacturer <u>N/A</u> Model <u>N/A</u> Serial # <u>N/A</u> ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____																			
Location of Asset: _____ For more information contact: _____ Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			