

# Vehicle Inspection Form

Inventory ID: <u>3795/278</u>	Asset Number:	Fair Market Value:
-------------------------------	---------------	--------------------

Short Description:  
 Year 1952      Make Dodge      Model Power Wagon

VIN: 

8	3	9	3	0	2	4	5										
---	---	---	---	---	---	---	---	--	--	--	--	--	--	--	--	--	--

 Title Restriction: ☐ Y ☒ N  
 Odometer: 

2	3	3	9	2	
---	---	---	---	---	--

☐ Miles ☐ Kilometers      Odometer Accurate ☐ Y ☒ N: \_\_\_\_\_

**Long Description:**  
 This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs/Driveable ☐ Engine Runs ☒ Does Not Run ☐ For Parts Only  
 Engine- Type:      L, V      ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid  
 Engine Condition: ☐ Runs ☐ Needs repair ☒ is in unknown condition  
 Repairs needed: \_\_\_\_\_

This vehicle was maintained every N/A ☐ Days ☐ Hours ☐ Miles  
 Date Removed From Service: N/A      Maintenance Records: ☐ Available ☐ Not Available For Inspection  
**Transmission:** ☐ Automatic ☒ Manual      Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition  
 Repairs Needed: \_\_\_\_\_  
**Drivetrain:** ☐ 2 Wheel Drive ☒ 4 Wheel Drive      Condition: \_\_\_\_\_

**Exterior:**      Color: Red      Windows: ☒ No Cracked Glass ☐ Cracked \_\_\_\_\_  
 Minor: ☒ Dents ☒ Scratches ☐ Dings      Tire Condition: Fair      Tread:      #Flat      Hubcaps #       
 Major Damage to: \_\_\_\_\_  
 Additional Damage: \_\_\_\_\_  
 Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☒ No Impressions  
 Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

**Interior:**      Color      ☒ Cloth ☐ Vinyl ☐ Leather  
 Damage to Seats: \_\_\_\_\_  
 Damage to Dash/Floor: \_\_\_\_\_  
 Radio: ☐ Stock or ☐ Brand & Model: N/A ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD  
☐ AC (Condition: ☐ Cold ☐ Unknown) ☒ No AC      Air Bags: ☐ Driver's Side ☐ Dual  
☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control  
 Power: ☐ Steering ☐ Windows ☐ Door Locks ☐ Seats

**Additional Equipment:** \_\_\_\_\_  
 Manufacturer \_\_\_\_\_ Model \_\_\_\_\_ Serial # \_\_\_\_\_  
☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand \_\_\_\_\_ ☐ Hitch: Type \_\_\_\_\_

**Location of Asset:** 39595 Hwy 145 Norwood CO 81423  
**For more information contact:** Rakona Runnel 970-327-4885  
**Reminder:** Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.