

## Generic Inspection Form

Inventory ID: \_\_\_\_\_

Asset Number \_\_\_\_\_

Anticipated Sale Price: \_\_\_\_\_

Short Description: Snow Blade for a 4 Wheeler

Year \_\_\_\_\_

Manufacturer Cycle Country

Model \_\_\_\_\_

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☐ Hours: \_\_\_\_\_ This equipment was maintained every \_\_\_\_\_ ☐ Hours ☐ Days

Serial # \_\_\_\_\_

Repairs needed: \_\_\_\_\_

### Description of Use

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Color Black ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: Blade Bent on one corner

Major damage to: \_\_\_\_\_

Size: Length: Feet: 5 Inches: \_\_\_\_\_ Width/Depth: Feet: \_\_\_\_\_ Inches: \_\_\_\_\_ Height: Feet: 1 Inches: 7

Men's Size: \_\_\_\_\_ Women's Size: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Additional Equipment: Manufacturer \_\_\_\_\_ Model \_\_\_\_\_

Serial # \_\_\_\_\_ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: \_\_\_\_\_

Comments:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Location of Asset: 1165 Summit Street Norwood CO 81423

For more information contact: Ramona Lummel 970-327-4885