

S MC TAG #3173

Vehicle Inspection Form

Inventory ID:

119

Asset Number:

Fair Market Value:

Short Description:

Year 1970

Make Hyster

Model

Iron wheel

VIN:

A 8 9 C 1 7 8 8 N

Title Restriction: ☐ Y ☐ N

N/A

Odometer:

☐ Miles☐ KilometersOdometer Accurate ☐ Y ☐ N:

Long Description:

This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs/Driveable ☐ Engine Runs ☒ Does Not Run ☐ For Parts OnlyEngine- Type: ☐ L, V ☐ Gas ☒ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric HybridEngine Condition: ☐ Runs ☐ Needs repair ☒ is in unknown condition

Repairs needed:

Cannot verify how motor

This vehicle was maintained every N/A ☐ Days ☐ Hours ☐ Miles

Date Removed From Service:

Maintenance Records: ☐ Available ☐ Not Available For InspectionTransmission: ☒ Automatic ☐ Manual ☐ Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed:

Drivetrain: ☐ 2 Wheel Drive ☐ 4 Wheel Drive Condition:

Exterior:

Color: Yellow

Windows: ☐ No Cracked Glass ☐ CrackedMinor: ☐ Dents ☐ Scratches ☐ Dings

Tire Condition: Tread: #Flat Hubcaps #

Major Damage to:

Additional Damage:

Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No ImpressionsEmergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior:

Color

☐ Cloth ☐ Vinyl ☐ Leather

Damage to Seats:

Damage to Dash/Floor:

Radio: ☐ Stock or ☐ Brand & Model: ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No ACAir Bags: ☐ Driver's Side ☐ Dual☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate ControlPower: ☐ Steering ☐ Windows ☐ Door Locks ☐ Seats

Additional Equipment:

Manufacturer Model Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand ☐ Hitch: Type

Location of Asset:

39595 Hwy 145 Norwood CO 81423

For more information contact:

Kamara Rummel 970-327-4885

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.