Fire Apparatus Inspection Form

Asset ID: 12328 | **Inventory ID:** V-6422 | **Fair Market Value:**

Short Description:
Year 2004 Manufacturer FORD Model F-350 SUPER DUTY

VIN: 3 F T S F 3 1 S 2 4 M A 0 2 3 1 3 Title Restriction: ☐ Y ☒ N

Mileage/Odometer: 1 3 9 4 3 Odometer Accurate ☒ Y ☐ N:_____

Long Description:

This Apparatus is a: ☐ Pumper ☐ Ladder ☐ Tanker ☐ Rescue ☐ HazMat ☐ Crash ☒ Other Brush Truck

☒ Starts ☐ Starts with a Boost & ☐ Runs ☐ Does Not Run: _____

Engine: Manufacture: Ford Size: 6.8 L, V 10 ☒ Gas ☐ Diesel Hours: _____

This Apparatus was maintained every 180 ☒ Days ☐ Hours

Engine Condition: ☒ Is operable ☐ Needs repair ☐ Is Unknown Condition

Engine Repairs Needed: _____

Transmission: Manufacture: Ford ☒ Automatic ☐ Manual___ Speed Hours _____

Transmission Condition: ☒ Is operable ☐ Needs repair ☐ Is in Unknown Condition

Transmission Repairs Needed: _____

Date Removed From Service: 11/21/2025 Maintenance Records: ☐ Available ☒ Not Available For Inspection

NOTE: PUMP AND LADDER CERTIFICATIONS ARE REQUIRED FOR SOME ADVERTISING

Ladder: Manufacture. _____ **Model** _____ **Serial #**_____

Length_____ **Last Tested**__/__/__

Ladder Certification ☐ Yes-Certification Expires ___/___/___ ☐ No Certification-Expired ___/___/___

Pump: Manufacture: _____ **Model** _____**Serial #**_____

Operable: ☐ Yes ☐ No **Hours**_____ **GPM**_____ **Last Tested**__/__/__

Pump Certification ☐ Yes-Certification Expires ___/___/___ ☐ No Certification-Expired ___/___/___

Additional Equip: ☐ **Tank Size:** _____**Gallons** ☐ Fiberglass ☐ Poly ☐ Metal ☐ **Hose** (Gauge____ Feet_____)

 # Of Intakes _____ **Location/Size** _____

 # Of Discharges _____ **Location/Size** _____

Tire Condition: ☐ **Good** ☒ **Fair** ☐ **Poor** ☐ **Low #**___ ☐ **Flat #**_____

Additional Features (Lights, Generators, Loose Equipment): Emergency Lights, Plow, Fire Pump Skid

_____

Exterior: Color Red/ White Chassis Red/White Body Red/ White **Windows**: ☒ Not Cracked ☐ Cracked _____

Minor ☒ Dents ☒ Scratches ☒ Dings Damage To: _____

Decals: ☐ None ☐ Have been sprayed ☒ Have been removed & ☐ Impressions remain ☒ No impressions

Interior: Color Gray ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats/Dash/Floor: Small rip in seat cover on the driver's side

Interior Equipment: Plow Controller, Custom console for siren controller and radio.