

Heavy Equipment Condition Report:

Asset Information:

Equipment Type:

Other: Vacuum truck

Unit No: 106984

Engine Information:

Year: 2009

Year: 2009

Make: Mack

Make: Mack

Model: GU713

Model: 12.7 L

VIN/SN: 1M2AX07Y19M006984

HP:

Miles/Hrs.: 216679

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Unknown

All Attachments Articulate Could not confirm

Notes:

Control Station Type: Enclosed Cab

AC/Heat: Yes

AC/Heat working: Could not confirm

Additional Equipment:

Chassis:

Powertrain Type: 2WD

Propulsion Type: Wheel, Pneumatic

Track Condition:

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size: Front: 11R24.5

Rear(s): 11R24.5

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe:

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes:

Location contact reported the truck has a fuel issue.