

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Skid Steer

Other: _____

Unit No: 37-0044

Year: 2014

Make: CAT

Model: 259D

VIN/SN: FTL02146

Miles/Hrs.: 4957

Engine Information:

Year: 2014

Make: CAT

Model: C3.3

HP: _____

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Canopy

AC/Heat: No

AC/Heat working: _____

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Track, Rubber

Track Condition: Fair - Track condition shows heavy use and may require maintenance

Wheel Condition: _____

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes:

took about an hour to get running, battery issue. Some rust