

Trailer Condition Report:

Equipment Information:

Unit No: _____
Year: 2018
Make: Salvation Trailers
Model: _____
VIN/SN: 7GG1E1626JW004021

Equipment Condition:

Mechanical Condition: Fair - Functioning, but in need of repair

Interior Condition: Fair - Functioning, but in need of repair

Chassis:

GVWR: 7,000 Suspension: Spring
Tire Size: _____ Sliding Tandem Axle: _____
Braking: _____
Comments: _____

Deck

Hitch Type: Ball
Dimensions: Length: 16' Width: 8.5'
Ramps (if equipped) _____

Specialized Equipment:

Type: _____ Details: _____
Type: _____ Details: _____

Notes: _____
Notes: _____