## **Heavy Equipment Condition Report:**

Equipment Type:	Compressor	t iiiioiiiiat		
Other:	·			
20-0057			Engine Information:	
2001		Year:	2001	
Ingersoll-Rand		Make:	John Deere	
P185WJD		Model:	4045DF150B	HP:
4FVCABBA21U319	683 / 319683UBL2221	SN:		
		Fuel Type:	Diesel	
	Ass	et Condition	on:	
anical Condition:	Poor - Will not start o	or operate and	d is in need of repair.	
terior Condition:	Fair - Interior is heavi	ly worn.		
terior Condition:	Fair - Visible dents an	d scratches		
s are Functional:	Yes	Hydra	nulic Leaks Present: No	
loves FWD/REV:	Neither			
ments Articulate	No	Notes:		
rol Station Type:	None	AC/Heat:	AC/Heat working:	
onal Equipment:	_			
		Chassis:		
		Giragoio.		
owertrain Type:		Gridosio		
ropulsion Type:	Wheel, Pneumatic	GITGGGTGT		
ropulsion Type: rack Condition:	·			
ropulsion Type: rack Condition: heel Condition:	Fair - Wheel condition		y use and may require maintenance	
ropulsion Type: rack Condition:	Fair - Wheel condition	n shows heav	Rear(s):	
ropulsion Type: rack Condition: heel Condition: Tire Size:	Fair - Wheel condition Front:	n shows heav ttachment	Rear(s):	
ropulsion Type: rack Condition: heel Condition: Tire Size:	Fair - Wheel condition	n shows heav ttachment	Rear(s):	
ropulsion Type: rack Condition: heel Condition: Tire Size:	Fair - Wheel condition Front:	n shows heav ttachment ently conne	Rear(s):	
ropulsion Type: rack Condition: heel Condition: Tire Size: Iditional attachme	Fair - Wheel condition Front:	n shows heav ttachment ently conne Details:	Rear(s):	
ropulsion Type: rack Condition: heel Condition: Tire Size:	Fair - Wheel condition Front:	n shows heav ttachment ently conne	Rear(s):	
ropulsion Type: rack Condition: heel Condition: Tire Size: Iditional attachme	Fair - Wheel condition  Front:  Attention  A	n shows heave ttachment rently conne Details: Details:	Rear(s): S cted to this asset?	
ropulsion Type: rack Condition: heel Condition: Tire Size: Iditional attachme	Fair - Wheel condition Front: Attents that are not currents  Add	n shows heav ttachment ently conne Details:	Rear(s): S cted to this asset?	
ropulsion Type: rack Condition: heel Condition: Tire Size: Iditional attachme	Fair - Wheel condition Front: Attents that are not currents  Add	n shows heave ttachment rently conne Details: Details:	Rear(s): S cted to this asset?	
2 1 1 ::	20-0057 2001 Ingersoll-Rand P185WJD 4FVCABBA21U319 anical Condition: terior Condition: terior Condition: s are Functional: Moves FWD/REV: ments Articulate rol Station Type:	Other:  20-0057  2001  Ingersoll-Rand P185WJD  4FVCABBA21U319683 / 319683UBL2221  Ass anical Condition: terior Condition:     Fair - Interior is heavi terior Condition:     Fair - Visible dents an     s are Functional:     Yes Moves FWD/REV:     Meither ments Articulate rol Station Type:     None	Other:  20-0057  2001	Other:  20-0057  Engine Information:  2001  Year: 2001  Ingersoll-Rand  Make: John Deere  P185WJD  Model: 4045DF150B  4FVCABBA21U319683 / 319683UBL2221  SN:  Fuel Type: Diesel  Asset Condition:  Anical Condition: Poor - Will not start or operate and is in need of repair.  Asir - Interior is heavily worn.  Aterior Condition: Fair - Visible dents and scratches  are Functional: Yes  Moves FWD/REV: Neither  ments Articulate No Notes:  rol Station Type: None AC/Heat: AC/Heat working:  onal Equipment: