

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Compressor

Other: _____

Unit No: 20-0070

Year: 2007

Make: Ingersoll-Rand

Model: P185WIR

VIN/SN: 382481UBR820

Miles/Hrs.: 6424

Engine Information:

Year: 2006

Make: Ingersoll-Rand

Model: 4IRI8N

HP: _____

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate: No

Notes: _____

Control Station Type: None

AC/Heat: _____ AC/Heat working: _____

Additional Equipment: _____

Chassis:

Powertrain Type: _____

Propulsion Type: Wheel, Pneumatic

Track Condition: _____

Wheel Condition: Good - Wheel condition shows normal wear from use

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: