

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: _____

Other: Sweeper

Unit No: 28-0055

Year: 2005

Make: Walden

Model: SM250

VIN/SN: 30718

Miles/Hrs.: 5082

Engine Information:

Year: _____

Make: Cummins

Model: _____ HP: _____

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: No

Unit Moves FWD/REV: Both

All Attachments Articulate Yes

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: _____

Additional Equipment: _____

Chassis:

Powertrain Type: 2WD

Propulsion Type: Wheel, Pneumatic

Track Condition: _____

Wheel Condition: Fair - Wheel condition shows heavy use and may require maintenance

Tire Size:

Front: ST225/75R15

Rear(s): ST225/75R15

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: _____

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: