

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Loader

Other: _____

Unit No: 6-2611

Year: 2012

Make: Volvo

Model: L180G

VIN/SN: 19634

Miles/Hrs.: 8912

Engine Information:

Year: 2012

Make: Volvo

Model: Diesel

SN: _____

HP: 269

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: Yes

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Yes

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition: _____

Wheel Condition: Good - Wheel condition shows normal wear from use

Tire Size: _____

Front: 26.5r25

Rear(s): 26.5r25

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: BUCKET

Type: BUCKET

Type: _____

Details: _____

Details: _____

Additional Notes:

Various hoses and ram seals weeping, low hydraulic fluid light on,