Heavy Equipment Condition Report:

Asset Information:		
Equipment Type:	Loader	
Other:		
Unit No: 6-2606	Engine Information:	
Year: 2011	Year: 2011	
Make: CAT	Make: Cat	
Model: 966K	Model: 9.3 HP: 2	67
VIN/SN: CAT0966KATFS001)112 SN:	
/liles/Hrs.: 14268	Fuel Type: Diesel	
Asset Condition:		
Mechanical Condition:	Good - Starts and operates; Some parts may require repair or replacement soon.	
Interior Condition:	Good - Damage is limited to normal wear and minor scratches.	
Exterior Condition:	Fair - Visible dents and scratches	
Hydraulics are Functional:	Yes Hydraulic Leaks Present: Yes	
Unit Moves FWD/REV: _		
All Attachments Articulate		
Control Station Type:		
Additional Equipment:		
	Chassis:	
Powertrain Type:	4WD	
Propulsion Type:	Wheel, Pneumatic - All Terrain	
Track Condition:		
Wheel Condition:	Good - Wheel condition shows normal wear from use	
Tire Size:	Front: 26.5r25 Rear(s): 26.5r25 Attachments	
Nuo thougodditional attachus		
	nents that are not currently connected to this asset?	
Describe: BUCKET	Deteile: Creeked	
Type: BUCKET	Details: Cracked	
Туре:	Details:	
Additional Notes:		
Various hoses and ram seals weaping, seveal exterior components damaged, cab wiring, hand rails		
various rioses ariu rairi sedis We	caping, sevear exterior components damaged, cab willing, hand rails	