

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: Loader

Other: _____

Unit No: _____

Engine Information:

Year: 2011

Year: 2011

Make: Caterpillar

Make: Cat

Model: 966K

Model: 9.3

HP: 267

VIN/SN: CAT0996KLTF00113

SN: _____

Miles/Hrs.: 12765

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: Yes

Unit Moves FWD/REV: Both

All Attachments Articulate: Yes

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Yes

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Wheel, Pneumatic - All Terrain

Track Condition: _____

Wheel Condition: Good - Wheel condition shows normal wear from use

Tire Size:

Front: 26.5r25

Rear(s): 26.5r25

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: BUCKET

Type: BUCKET

Details: Cracked

Type: _____

Details: _____

Additional Notes:

Various hoses and ram seals weeping, seat torn