

# Heavy Equipment Condition Report:

## Asset Information:

Equipment Type: Loader

Other: \_\_\_\_\_

Unit No: \_\_\_\_\_

Engine Information:

Year: \_\_\_\_\_

Year: 2020

Make: Komatsu

Make: SAA6D125E-7

Model: WA470-8

Model: Komatsu

HP: 272

VIN/SN: A49669

SN: \_\_\_\_\_

Miles/Hrs.: 10761

Fuel Type: \_\_\_\_\_

## Asset Condition:

Mechanical Condition:

Interior Condition:

Exterior Condition:

Hydraulics are Functional:

Hydraulic Leaks Present:

Unit Moves FWD/REV:

All Attachments Articulate

Notes: \_\_\_\_\_

Control Station Type: None

AC/Heat: Yes AC/Heat working: N/A

Additional Equipment: \_\_\_\_\_

## Chassis:

Powertrain Type:

Propulsion Type:

Track Condition:

Wheel Condition:

Tire Size: Front:

Rear(s):

## Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: Bucket

Type: \_\_\_\_\_

Details: \_\_\_\_\_

Type: \_\_\_\_\_

Details: \_\_\_\_\_

## Additional Notes: