

Vehicle Inspection Form

Inventory ID: 3919

Asset Number: 4050

Fair Market Value:

Short Description:

Year 2007 Make CHEVROLET Model C7500 Hoist.

VIN: 1GBP7C1B27F422410 Title: ☒ Clean Title ☐ Salvage Title ☐ No Title
☐ Court Documents Only ☐ SF97 Form ☐ Other

Odometer: 166994 ☒ Miles ☐ Kilometers ☐ Hours Odometer Accurate? ☐ Yes ☐ No ☐ Unknown

Long Description:

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☐ Runs/Drivable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 7.8 L, V ☐ Gas ☒ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☐ Runs ☒ Needs repair ☐ is in unknown condition

Repairs needed: Engine runs Hot and has Coolant Leak

This vehicle was maintained every 12 months ☐ Days ☐ Hours ☐ Miles/Kilometers

Date Removed from Service: 2025 Maintenance Records: ☐ Available ☒ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed:

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition:

Exterior: Color: White/Black Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: Tread: #Flat Hubcaps #

Major Damage to:

Additional Damage: hood damage - head lamp missing

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No impressions

Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color Gray ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: none

Damage to Dash/Floor: none

Radio: ☒ Stock or ☐ Brand & Model: ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☐ Cold ☒ Unknown ☐ No AC

Air Bags: ☐ Driver's Side ☐ Dual

☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☒ Climate Control

Power: ☒ Steering ☐ Windows ☐ Door Locks ☐ Seats

Additional Equipment:

Manufacturer Model Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand Hitch: Type

Location of Asset: