

Vehicle Inspection Form

Inventory ID: 3753

Asset Number: 8554

Fair Market Value:

Short Description:

Year 2006 Make John Deere Model 5225

VIN: LV52255320036

Title: ☐ Clean Title ☐ Salvage Title ☒ No Title

☐ Court Documents Only ☐ SF97 Form ☐ Other

Odometer: 9669 ☐ Miles ☐ Kilometers ☒ Hours Odometer Accurate? ☐ Yes ☐ No ☐ Unknown

Long Description:

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Drivable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 3.1 L, V ☐ Gas ☒ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed:

This vehicle was maintained every 200 ☐ Days ☒ Hours ☐ Miles/Kilometers

Date Removed from Service: 2025 Maintenance Records: ☐ Available ☒ Not Available For Inspection

Transmission: ☐ Automatic ☒ Manual ☐ Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed:

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition:

Exterior:

Color: Green

Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☐ Dents ☒ Scratches ☒ Dings

Tire Condition: Good ad: #Flat Hubcaps #

Major Damage to:

Additional Damage:

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No impressions

Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior:

Color: Gray

☒ Cloth ☐ Vinyl ☐ Leather

Damage to Seats: none

Damage to Dash/Floor: none

Radio: ☒ Stock or ☐ Brand & Model: ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☐ Cold ☒ Unknown ☐ No AC

Air Bags: ☐ Driver's Side ☐ Dual

☐ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☐ Windows ☐ Door Locks ☐ Seats

Additional Equipment:

Manufacturer _____ Model _____ Serial # _____

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____

Location of Asset: _____