

GovDeals

AWD / 4X4

Lot Space # _____ Summs Reference No. 348353

Client <u>Chesapeake</u>		Vehicle Info	
Customer Name _____		Year <u>2014</u> Make <u>Ford</u> Color <u>White</u>	
Asset # <u>CH075</u>		Model <u>FUSION</u> Doors <u>4</u> Ebrake: Yes / No	
Unit Secured From <u>156 Greenbrier Pkwy Ches</u>		License No. _____ State _____ Exp. Date _____	
		Mileage <u>81661</u> ☐ Won't Display	
		Heavy Damage: Yes / No	
Date Recovered <u>1/20/26</u>		P/U By <u>971</u> Tow By & Truck # <u>104</u>	☒ Ignition ☐ Transponder ☐ Push Button ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start
Time: _____ AM or PM			
Storage Address:			
☒ Summs Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454			
Release Hours By Appointment Only			

VIN 1FA6P0G76E5366831

	Completed While		☐ Sunny ☐ Frost on Car ☐ Rainy/Wet ☐ Snow ☐ Iced Over ☐ Night		EQUIPMENT ☐ Rear A/C ☐ 3rd Row ☐ Navigation ☐ Backup Camera ☐ Heated Seats ☐ Cooled Seats ☐ Power Windows ☐ Power Seats ☐ Power Door Locks ☐ Power Mirrors ☐ Cruise Control ☐ Tilt Wheel ☐ Sun Roof ☐ AM FM ☐ CD ☐ DVD ☐ Amp Subwoofer ☐ Touch Display ☐ Leather Seats ☐ EV Charger ☐ Breathalyzer ☐ Trailer Hitch ☐ Bed Liner ☐ Step Rails ☐ Tool Box Locked Yes / No ☐ Bed Cover or Cap Locked Yes / No ☐ Hubcaps # <u>4</u> ☐ Factory Rims ☐ Aftermarket Rims																																	
	General Condition of Collateral		☐ Good ☐ Average ☐ Poor																																			
	M E C H A N I C A L Engine ☒ OK ☐ Rough ☐ Burns Oil Transmission ☒ OK ☐ Slips ☐ Leaks Oil Clutch ☐ OK ☐ Fair ☐ Slips Brakes ☐ OK ☒ Fair ☐ Pull Grab Battery ☒ Yes ☐ No ☒ OK ☐ Dead ☐ Disc.. Engine Intact ☒ Yes ☐ No This condition report was completed by a non mechanic and unit not road tested.																																					
	T I R E S <table border="1"> <thead> <tr> <th></th> <th>Good</th> <th>Fair</th> <th>Poor</th> <th>None</th> </tr> </thead> <tbody> <tr> <td>L. Front</td> <td>☒</td> <td></td> <td></td> <td></td> </tr> <tr> <td>L. Rear</td> <td>☒</td> <td></td> <td></td> <td></td> </tr> <tr> <td>R. Front</td> <td>☒</td> <td></td> <td></td> <td></td> </tr> <tr> <td>R. Rear</td> <td>☒</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Spare</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>			Good		Fair	Poor	None	L. Front	☒				L. Rear	☒				R. Front	☒				R. Rear	☒				Spare									
	Good	Fair	Poor	None																																		
L. Front	☒																																					
L. Rear	☒																																					
R. Front	☒																																					
R. Rear	☒																																					
Spare																																						
G L A S S <table border="1"> <thead> <tr> <th></th> <th>OK</th> <th>Crk</th> <th>Chip</th> <th>Missing</th> </tr> </thead> <tbody> <tr> <td>Windshield</td> <td>☒</td> <td></td> <td></td> <td></td> </tr> <tr> <td>L. Front</td> <td></td> <td></td> <td>☒</td> <td></td> </tr> <tr> <td>L. Rear</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>R. Front</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>R. Rear</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Rearview</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>			OK	Crk	Chip	Missing	Windshield	☒				L. Front			☒		L. Rear					R. Front					R. Rear					Rearview						
	OK	Crk	Chip	Missing																																		
Windshield	☒																																					
L. Front			☒																																			
L. Rear																																						
R. Front																																						
R. Rear																																						
Rearview																																						
I N T E R I O R <table border="1"> <thead> <tr> <th></th> <th>Good</th> <th>Fair</th> <th>Poor</th> <th>None</th> </tr> </thead> <tbody> <tr> <td>Inst Panel</td> <td>☒</td> <td></td> <td></td> <td></td> </tr> <tr> <td>F. Seats</td> <td>☒</td> <td></td> <td></td> <td></td> </tr> <tr> <td>R. Seats</td> <td>☒</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Door Panels</td> <td>☒</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Mat Carpet</td> <td>☒</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Headliner</td> <td>☒</td> <td></td> <td></td> <td></td> </tr> </tbody> </table>			Good	Fair	Poor	None	Inst Panel	☒				F. Seats	☒				R. Seats	☒				Door Panels	☒				Mat Carpet	☒				Headliner	☒					
	Good	Fair	Poor	None																																		
Inst Panel	☒																																					
F. Seats	☒																																					
R. Seats	☒																																					
Door Panels	☒																																					
Mat Carpet	☒																																					
Headliner	☒																																					

Comments _____ _____ _____ _____ _____	Auction/Dealer Receipt for Repossession Date _____ Time _____ The undersigned acknowledges receipt of the above described vehicle in identical condition listed above. Printed Name _____ Signature _____ Witness _____
--	---