

Lot Space # _____ Summs Reference No. 3419-73

Client <u>City of Chesapeake</u> Lien Holder Customer Name _____ Asset # <u>E1096</u> Unit Secured From <u>956 Greenbrier Pkwy</u>		Vehicle Info Year <u>2007</u> Make <u>Chery</u> Color <u>white</u> Model <u>Impala</u> Doors _____ Ebrake: Yes / No License No. _____ State _____ Exp. Date _____ Mileage <u>136890</u> ☐ Won't Display Lasso lock: Yes / No Heavy Damage: Yes / No Airbags Deployed: Yes / No	
Date Recovered <u>10/22/25</u> Time: <u>3:00</u> AM or PM <u>PM</u> Storage Address: ☒ Surams Skip and Collateral Solutions 2616 Quality Court Virginia Beach, VA 23454 Release Hours By Appointment Only		P/U By <u>971</u> Tow By & Truck # <u>104</u> Tow from For R Used ☐ Go Jacks ☐ Dolly ☐ Roll Back ☐ None ☐ Shift Lock Customer Aware? <u>Yes/No</u> Able to Get Into Unit? <u>Yes/No</u> Insp _____ Vehicle Locked at Time of Repo? <u>Yes/No</u> Fuel: E, 1/4, 1/2, 3/4, F Personals? <u>Yes/No</u> Glove/Center Box Access <u>Yes/No</u> Trunk Access? <u>Yes/No</u> Keys? <u>Yes/No</u> How Many _____ How Many FOBS _____	
		K ☐ Ignition E ☐ Transponder V ☐ Push Button S ☐ No Key ☐ FOB ☐ Keys ☐ Has Keys Does not Run or Start	

VIN	2	G	1	W	S	5	5	R	8	7	9	1	9	9	2	8	3
-----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

A hand-drawn diagram of a car's body panels, showing the layout of various components. The diagram is symmetrical and includes the following labels and handwritten markings:

- Front Bumper** (top center)
- Head Light** (top left and top right)
- Side of Fender** (left and right sides, near the head lights)
- Top of Fender** (left and right sides, above the side of fender)
- Hub Cap** (left and right sides, near the wheels)
- Grill** (center, below the front bumper)
- Hood** (center, below the grill)
- Windshield** (center, below the hood)
- Top of Cab** (center, below the windshield)
- Cowl** (left and right sides, below the top of cab)
- Front Door** (left and right sides, below the cowl)
- Window** (left and right sides, between the front and rear doors)
- Rear Door** (left and right sides, below the front door)
- Top of Fender** (left and right sides, below the rear door)
- Window** (left and right sides, between the rear door and the rear window)
- Rear Window** (center, below the top of fender)
- Trunk or Hatch Bed** (center, below the rear window)
- Side of Fender** (left and right sides, near the rear wheel)
- Tail Light** (left and right sides, near the rear wheel)
- Hub Cap** (left and right sides, near the rear wheel)
- Back Bumper** (bottom center)

Handwritten blue numbers are placed on the diagram:

- 9** (on the left side of the front fender)
- 5** (on the center hood)
- 9** (on the left side of the front door)
- 5** (on the right side of the front door)
- 5** (on the right side of the rear door)
- 5** (on the left side of the rear fender)
- 5** (on the center trunk/hatch bed)
- 5** (on the bottom back bumper)

Completed While		General Condition of Collateral		Engine		Rough		Burns Oil	
Sunny ☐ Frost on Car ☐ Rainy/Wet ☐ Snow ☐ Ice Over ☐ Night ☐		Good ☐ Average ☐ Poor ☐		☐ OK ☐ No		☐ OK ☐ Dead		☐ Disc..	
M E C H A N I C A L		Engine Intact ☒ Yes ☐ No		This condition report was completed by a non mechanic and unit not road tested.					
T I R E S		☒ Good ☐ Fair ☐ Poor ☐ None		EQUIPMENT					
L. Front		☒		☐ A/C		☐ Real A/C			
L. Rear		☒		☒ Auto Trans		☐ 3rd Row			
R. Front		☒		☐ Manual Trans		☐ Navigation			
R. Rear		☒		☒ Power Steering		☐ Backup Camera			
Spare		☒		☒ Power Brakes		☐ Heated Seats			
☐ Jack ☐ Spare Wheel ☐ Duals		☐		☐ Power Windows		☐ Cooled Seats			
		☐		☐ Power Seats					
		☐		☐ Power Door Locks					
		☐		☐ Power Mirrors					
		☐		☐ Cruise Control					
		☐		☐ Tilt Wheel					
		☐		☐ Sun Roof					
		☐		☒ AM FM ☐ CD ☐ DVD					
		☐		☐ Amp Subwoofer					
		☐		☐ Touch Display					
		☐		☐ Leather Seats					
		☐		☐ EV Charger					
I N T E R I O R		☒ Good ☐ Fair ☐ Poor ☐ None		☐ Breathalyzer ☐ Trailer Hitch ☐ Bed Liner ☐ Step Rails ☐ Tool Box Locked Yes / No ☐ Bed Cover or Cap Locked Yes / No ☐ Hubcaps # <u>4</u> ☒ Factory Rims ☐ Aftermarket Rims					
Inst Panel		☒							
F. Seats		☒							
R. Seats		☒							
Door Panels		☒							
Mat Carpet		☒							
Headliner		☒							

Completed By	Date
Comments	

Auction/Dealer Receipt for Repossession
 Date _____ Time _____
 The undersigned acknowledges receipt of the above
 described vehicle in identical condition listed above.
 Printed Name _____
 Signature _____
 Witness _____